

Interceptor Condition Assessment and Rehabilitation Program

Scott Dentz, Manager Interceptor Engineering and Design
Karen Keenan, Manager Interceptor Project Delivery

Environment Committee


February 11, 2014



Topics

- Current System
- Condition Assessment
- Rehabilitation Program

CCTV INSPECTIONS 2003 - 2013




Inspection Status


- 481 miles of gravity sewer in MCES system
- 317 miles inspected (pink) 2003 through 2013
- 164 miles to be inspected in 2014-2015

Interceptor Type


Total Footage of Interceptor



Pipe Age



Pipe Material



GRAVITY PIPE MATERIAL

- CONCRETE
- LINED
- PLASTIC
- GLASS
- CLAY
- BRICK
- OTHER
- METAL
- SR TUNNEL

Condition Assessment Program

- Inspect All Gravity Sewer Pipe within a 10-Year Cycle
- Evaluate Pipe Condition Using Standardized Rating System
- Re-inspect Deteriorated Pipe at More Frequent Intervals
- Devise and Implement Inspection Program for Force Main and River Crossing Facilities

Condition Grading System

Grade	Condition	Rehabilitation
5	Near failure	Immediate Attention
4	Poor	Repair within 10 years
3	Fair	Re-inspect in 5 years
2	Good	Re-inspect in 10 years
1	Excellent	Re-inspect in 10 years



Reasons for Poor Pipe Condition

- Hydrogen Sulfide (H₂S) Corrosion
 - Long travel time produces septic wastewater and high concentrations of dissolved sulfides that when released cause corrosion damage.
 - High pipe slope found in areas with steep terrain produces turbulence that releases H₂S.
 - Force mains produce septic wastewater, H₂S is released when discharged into the downstream gravity sewer.
 - Turbulence where flow drops into a lower pipe.
 - Junctions where multiple pipes meet.
- Pipe Materials
 - Concrete and metal pipe do not hold up to H₂S Corrosion.
 - Vitrified clay while resistant to H₂S corrosion is brittle and cannot tolerate subsidence. Results in open joints and cracked pipe.
- Poor Soils
 - Pipe alignment traverse or follow areas or poor soil such as wetlands and natural drainage paths.

Rehabilitation Technologies

- Pipe
 - Cured-In-Place-Pipe
 - Slip-lining
 - Remove and Replace
- Maintenance Structures
 - Lining (cured-in-place)
 - Fiberglass Lining Inserts
 - Polymer Concrete Inserts
 - Coating Systems

Construction Materials

- Pipe
 - Reinforced Plastic Mortar Pipe
 - Polyvinyl Chloride Pipe
 - High Density Polyethylene Pipe
 - Epoxy Lined Ductile Iron Pipe
 - Cured-In-Place Lined Reinforced Concrete Pipe
- Maintenance Access Structures
 - Fiberglass
 - Polymer Concrete
 - Cured-In-Place Lined Reinforced Concrete

Lessons Learned

- Corrosion damage occurs in bare concrete and metal pipe (73 percent of existing system)
- Corrosion damage occurs downstream of force main discharges
- Corrosion damage occurs in areas of turbulence, such as pipe with high slopes and at drop locations

Current Approach for New Interceptors

- Use corrosion resistant materials
- Use chemicals, oxygen/ozone injection to reduce the sulfides in the wastewater
- Minimize force main length
- Minimize turbulence— minimize use of drops and highly sloped pipe

Interceptor System Proposed 2014-2019 CIP

- Asset Preservation
 - 90 Miles of Pipe
 - 20 Lift Stations
- Growth/Capacity
 - 3 Miles of Pipe
 - 5 Lift Stations
- Proposed Investment
 - \$604 Million

Category 5




Category 4



Category 3



Category 2




Category 1



Corrosion Damage Found at FM Discharge Structure



Corrosion Damage Found at Highly Sloped Concrete Pipe



Corrosion Damage Metal Pipe



Overly Deflected PVC Pipe



Subsidence in Poor Soils

