

Application

04776 - 2016 Bridges

04849 - CSAH 81 (West Broadway Avenue/Bottineau Boulevard) Bridge Replacement over Lowry Avenue/Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway

Regional Solicitation - Roadways Including Multimodal Elements

Status:

Submitted

Submitted Date:

07/14/2016 12:35 PM

Primary Contact

Name:*	Salutation	Carla First Name	J Middle Name	Stueve Last Name
Title:	Transportation	Transportation Engineer		
Department:				
Email:	Carla.Stueve@hennepin.us			
Address:	1600 Prairie Drive			
*	Medina	Minneso	ta	55340
	City	State/Provinc	e	Postal Code/Zip
Phone:*	612-596-0356			
	Phone		Ext.	
Fax:				
What Grant Programs are you most interested in?	Regional Solicitation - Roadways Including Multimodal Elements			

Organization Information

Name:	HENNEPIN COUNTY		
Jurisdictional Agency (if different):			
Organization Type:	County Government		
Organization Website:			
Address:	DPT OF PUBLIC WORKS		
	1600 PRAIRIE DR		
*	MEDINA	Minnesota	55340
	City	State/Province	Postal Code/Zip
County:	Hennepin		
Phone:*	763-745-7600		
		Ext.	
Fax:			
PeopleSoft Vendor Number	0000028004A9		

Project Information

	CSAH 81 (West Broadway Avenue/Bottineau Boulevard)		
Project Name	Bridge Replacement over Lowry Avenue/Oakdale Avenue and		
	Victory Memorial Drive/Theodore Wirth Parkway		
Primary County where the Project is Located	Hennepin		
Jurisdictional Agency (If Different than the Applicant):	Hennepin		

Brief Project Description (Limit 2,800 characters; approximately 400 words)

The project includes a full replacement of the pair of CSAH 81 (West Broadway Avenue/Bottineau Boulevard) bridges, including the northbound (No. 27008) and southbound (No. 27007) bridges. These bridges are located on an A-Minor Arterial roadway that currently carries 12,100 vehicles per day and is located on the border of Minneapolis and Robbinsdale. CSAH 81 is a significant regional corridor, supporting local and regional economic development and is located immediately south of the North Memorial Medical Center, which is one of three Level I Trauma Centers in the Twin Cities metropolitan area, and is the City of Robbinsdale's largest employer with approximately 3,500 employees. The corridor continues to experience increasing traffic volumes due to growth and redevelopment.

The current bridge designs are hinged concrete box girders that extend over Lowry Avenue/Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway. The existing bridges are exhibiting significant deterioration due to chloride infiltration resulting in extensive spalls and reinforcement corrosion at the hinges and abutments. Many of the spalled areas have exposed the reinforcement bars, which are exhibiting section loss. Water, chlorides and debris trapped in the hinge joints, have also caused similar deterioration to the bottom slab of the box sections. If the hinges crack completely, the concern is that the load transfer will be lost and the bridges will experience increased stresses for which they were not designed. Both CSAH 81 bridges are classified as structurally deficient, with the southbound bridge currently load posted. These bridges have the following structurally deficient sufficiency ratings:

Northbound CSAH 81 Bridge (27008): 44.2

Southbound CSAH 81 Bridge (27007): 24.9 (load posted)

For CSAH 81 to continue to deliver safe and efficient transportation service to its users, the project includes a full replacement of these deteriorated bridges with an upgraded design. The current width of these bridges is 35.5 feet, with a pavement width of 30 feet. There are currently two 12-foot travel lanes and two 3-foot shoulders. There is no space on the bridges for pedestrian or bicycle traffic. The new bridges would be designed with a wider cross section to accommodate additional traffic modes. The proposed cross section will include two 12-foot travel lanes, two 4-foot shoulders and a protected shared-use facility for pedestrians and bicyclists on each bridge. The curb barrier and railing would also be upgraded to provide a safer design. The bridge would be designed for a 75-year or greater service life.

Include location, road name/functional class, type of improvement, etc.

TIP Description Guidance (will be used in TIP if the project is	CSAH 81 OVER LOWRY AVE - REPLACE BR 27007 & 27008
selected for funding)	
Project Length (Miles)	0.15

Project Funding

Are you applying for funds from another source(s) to implement this project?	No
If yes, please identify the source(s)	
Federal Amount	\$7,000,000.00
Match Amount	\$6,500,000.00
Minimum of 20% of project total	
Project Total	\$13,500,000.00
Match Percentage	48.15%
Minimum of 20%	

Compute the match percentage by dividing the match amount by the project total

Source of Match Funds

Hennepin County and State

A minimum of 20% of the total project cost must come from non-federal sources; additional match funds over the 20% minimum can come from other federal sources

Preferred Program Year Select one: 2021 For TDM projects, select 2018 or 2019. For Roadway, Transit, or Trail/Pedestrian projects, select 2020 or 2021. Additional Program Years: Select all years that are feasible if funding in an earlier year becomes available.

Project Information-Roadways

County, City, or Lead Agency	Hennepin County		
Functional Class of Road	Minor Arterial (Augmentor)		
Road System	CSAH		
TH, CSAH, MSAS, CO. RD., TWP. RD., CITY STREET			
Road/Route No.	81		
i.e., 53 for CSAH 53			
Name of Road	West Broadway Avenue/Bottineau Boulevard		
Example; 1st ST., MAIN AVE			
Zip Code where Majority of Work is Being Performed	55422		
(Approximate) Begin Construction Date	04/15/2021		
(Approximate) End Construction Date	11/15/2021		
TERMINI:(Termini listed must be within 0.3 miles of any work)			
From: (Intersection or Address)	Abbott Avenue		
To: (Intersection or Address)	30th Avenue		
DO NOT INCLUDE LEGAL DESCRIPTION			
Or At			
Primary Types of Work	Full Bridge Replacement		
Examples: GRADE, AGG BASE, BIT BASE, BIT SURF, SIDEWALK, CURB AND GUTTER,STORM SEWER, SIGNALS, LIGHTING, GUARDRAIL, BIKE PATH, PED RAMPS, BRIDGE, PARK AND RIDE, ETC.			
BRIDGE/CULVERT PROJECTS (IF APPLICABLE)			
Old Bridge/Culvert No.:	27007 and 27008		
New Bridge/Culvert No.:			
Structure is Over/Under (Bridge or culvert name):			

Specific Roadway Elements

CONSTRUCTION PROJECT ELEMENTS/COST ESTIMATES	Cost
Mobilization (approx. 5% of total cost)	\$0.00
Removals (approx. 5% of total cost)	\$0.00
Roadway (grading, borrow, etc.)	\$0.00
Roadway (aggregates and paving)	\$0.00
Subgrade Correction (muck)	\$0.00
Storm Sewer	\$0.00
Ponds	\$0.00
Concrete Items (curb & gutter, sidewalks, median barriers)	\$0.00
Traffic Control	\$0.00
Striping	\$0.00
Signing	\$0.00
Lighting	\$0.00
Turf - Erosion & Landscaping	\$0.00
Bridge	\$13,500,000.00
Retaining Walls	\$0.00
Noise Wall (do not include in cost effectiveness measure)	\$0.00
Traffic Signals	\$0.00
Wetland Mitigation	\$0.00
Other Natural and Cultural Resource Protection	\$0.00
RR Crossing	\$0.00
Roadway Contingencies	\$0.00
Other Roadway Elements	\$0.00
Totals	\$13,500,000.00

Specific Bicycle and Pedestrian Elements

CONSTRUCTION PROJECT ELEMENTS/COST ESTIMATES	Cost
Path/Trail Construction	\$0.00
Sidewalk Construction	\$0.00
On-Street Bicycle Facility Construction	\$0.00
Right-of-Way	\$0.00
Pedestrian Curb Ramps (ADA)	\$0.00

Crossing Aids (e.g., Audible Pedestrian Signals, HAWK)	\$0.00
Pedestrian-scale Lighting	\$0.00
Streetscaping	\$0.00
Wayfinding	\$0.00
Bicycle and Pedestrian Contingencies	\$0.00
Other Bicycle and Pedestrian Elements	\$0.00
Totals	\$0.00

Specific Transit and TDM Elements

CONSTRUCTION PROJECT ELEMENTS/COST ESTIMATES	Cost
Fixed Guideway Elements	\$0.00
Stations, Stops, and Terminals	\$0.00
Support Facilities	\$0.00
Transit Systems (e.g. communications, signals, controls, fare collection, etc.)	\$0.00
Vehicles	\$0.00
Contingencies	\$0.00
Right-of-Way	\$0.00
Other Transit and TDM Elements	\$0.00
Totals	\$0.00

Transit Operating Costs

Number of Platform hours	0
Cost Per Platform hour (full loaded Cost)	\$0.00
Substotal	\$0.00
Other Costs - Administration, Overhead,etc.	\$0.00

Totals	

Total Cost	\$13,500,000.00
Construction Cost Total	\$13,500,000.00
Transit Operating Cost Total	\$0.00

Requirements - All Projects

All Projects

1. The project must be consistent with the goals and policies in these adopted regional plans: Thrive MSP 2040 (2014), the 2040 Transportation Policy Plan, the 2040 Regional Parks Policy Plan (2015), and the 2040 Water Resources Policy Plan (2015).

Check the box to indicate that the project meets this requirement. Yes

2. The project must be consistent with the 2040 Transportation Policy Plan. Reference the 2040 Transportation Plan objectives and strategies that relate to the project.

The CSAH 81 bridge replacement project is consistent with the 2040 Transportation Policy Plan by meeting the following objectives and strategies:

A) Transportation System Stewardship: Through Hennepin County's annual bridge inspection program we ensure planned preservation and maintenance of our facilities. This project would fully replace two structurally deficient bridges with a design for a 75+ year service life.

B) Safety and Security: The upgraded bridge design would provide a safer bridge deign to serve its users and will provide a wider cross section to accommodate a shared-use facility for pedestrians and bicyclists, in addition to a curb barrier and railing.

C) Access to Destinations: CSAH 81 is an A-Minor Arterial that functions as an augmenter and carries 12,100 vehicles per day. This roadway provides a vital connection in a fully developed, mature section of the metro area, and is regionally significant for the greater transportation network. These bridges support local transit routes 14 & 32 and provide a critical link for emergency vehicles for the North Memorial Level 1 Trauma Hospital that is located immediately to the north.

D) Competitive Economy: CSAH 81 is a significant regional corridor, supporting local and regional economic development. It is located immediately south of the North Memorial Medical Center, which is one of three Level I Trauma Centers in the Twin Cities metropolitan area, and is the City of Robbinsdale's largest employer with approximately 3,500 employees. The corridor continues to experience increasing traffic volumes due to growth

List the goals, objectives, strategies, and associated pages:

and redevelopment.

E) Healthy Environment: The proposed replacement of the CSAH 81 bridges includes a shared-use bicycle and pedestrian facility, creating a connection where previously there had been none, thusly creating an alternative transportation mode.

F) Leveraging Transportation Investments to Guide Land Use: The upgraded bridge design will support multi-modal traffic, with the addition of pedestrian and bicycle accommodations. This will provide an alternative local transportation connection bridging mature, walkable neighborhoods. This improved facility will also have the potential to support redevelopment in the project area.

3. The project or the transportation problem/need that the project addresses must be in a local planning or programming document. Reference the name of the appropriate comprehensive plan, regional/statewide plan, capital improvement program, corridor study document [studies on trunk highway must be approved by the Minnesota Department of Transportation and the Metropolitan Council], or other official plan or program of the applicant agency [includes Safe Routes to School Plans] that the project is included in and/or a transportation problem/need that the project addresses.

Top 20 Hennepin County Bridge Priority Ranking

MnDOT Bridge Inspection Report (pages attached)

List the applicable documents and pages:

MnDOT Structure Inventory Report (pages attached)

4. The project must exclude costs for studies, preliminary engineering, design, or construction engineering. Right-of-way costs are only eligible as part of bicycle/pedestrian projects, transit stations/stops, transit terminals, park-and-ride facilities, or pool-and-ride lots. Noise barriers, drainage projects, fences, landscaping, etc., are not eligible for funding as a standalone project, but can be included as part of the larger submitted project, which is otherwise eligible.

Check the box to indicate that the project meets this requirement. Yes

5. Applicants that are not cities or counties in the seven-county metro area with populations over 5,000 must contact the MnDOT Metro State Aid Office prior to submitting their application to determine if a public agency sponsor is required.

Check the box to indicate that the project meets this requirement. Yes

6.Applicants must not submit an application for the same project elements in more than one funding application category.

Check the box to indicate that the project meets this requirement. Yes

7. The requested funding amount must be more than or equal to the minimum award and less than or equal to the maximum award. The cost of preparing a project for funding authorization can be substantial. For that reason, minimum federal amounts apply. Other federal funds may be combined with the requested funds for projects exceeding the maximum award, but the source(s) must be identified in the application. Funding amounts by application category are listed below.

Roadway Expansion: \$1,000,000 to \$7,000,000

Roadway Reconstruction/ Modernization: \$1,000,000 to \$7,000,000

Roadway System Management \$250,000 to \$7,000,000

Bridges Rehabilitation/ Replacement: \$1,000,000 to \$7,000,000

Check the box to indicate that the project meets this requirement. Yes

8. The project must comply with the Americans with Disabilities Act.

Check the box to indicate that the project meets this requirement. Yes

9. The project must be accessible and open to the general public.

Check the box to indicate that the project meets this requirement. Yes

10. The owner/operator of the facility must operate and maintain the project for the useful life of the improvement.

Check the box to indicate that the project meets this requirement. Yes

11. The project must represent a permanent improvement with independent utility. The term independent utility means the project provides benefits described in the application by itself and does not depend on any construction elements of the project being funded from other sources outside the regional solicitation, excluding the required non-federal match. Projects that include traffic management or transit operating funds as part of a construction project are exempt from this policy.

Check the box to indicate that the project meets this requirement. Yes

12. The project must not be a temporary construction project. A temporary construction project is defined as work that must be replaced within five years and is ineligible for funding. The project must also not be staged construction where the project will be replaced as part of future stages. Staged construction is eligible for funding as long as future stages build on, rather than replace, previous work.

Check the box to indicate that the project meets this requirement. Yes

13. The project applicant must send written notification regarding the proposed project to all affected state and local units of government prior to submitting the application.

Check the box to indicate that the project meets this requirement. Yes

Roadways Including Multimodal Elements

1.All roadway and bridge projects must be identified as a Principal Arterial (Non-Freeway facilities only) or A-Minor Arterial as shown on the latest TAB approved roadway functional classification map.

Check the box to indicate that the project meets this requirement. Yes

Roadway Expansion and Reconstruction/Modernization projects only:

2. The project must be designed to meet 10-ton load limit standards.

Check the box to indicate that the project meets this requirement. Yes

Bridge Rehabilitation/Replacement projects only:

3.Projects requiring a grade-separated crossing of a Principal Arterial freeway must be limited to the federal share of those project costs identified as local (non-MnDOT) cost responsibility using MnDOTs Cost Participation for Cooperative Construction Projects and Maintenance Responsibilities manual. In the case of a federally funded trunk highway project, the policy guidelines should be read as if the funded trunk highway route is under local jurisdiction.

Check the box to indicate that the project meets this requirement. Yes

4. The bridge must carry vehicular traffic. Bridges can carry traffic from multiple modes. However, bridges that <u>are exclusively</u> for bicycle or pedestrian traffic must apply under one of the Bicycle and Pedestrian Facilities application categories. Rail-only bridges are ineligible for funding.

Check the box to indicate that the project meets this requirement. Yes

5. The length of the bridge must equal or exceed 20 feet.

Check the box to indicate that the project meets this requirement. Yes

6. The bridge must have a sufficiency rating less than 80 for rehabilitation projects and less than 50 for replacement projects. Additionally, the bridge must also be classified as structurally deficient or functionally obsolete.

Check the box to indicate that the project meets this requirement. Yes

Requirements - Roadways Including Multimodal Elements

Measure A: Functional Classification

Area	0.624
Project Length	0.154
Average Distance	4.0519
Upload Map	1466525015893_CSAH 081 (Broadway Ave) Bridge - Roadway Area.pdf

Measure B: Project Location Relative to Jobs, Manufacturing, and Education

Existing Employment within 1 Mile:	12868
Existing Manufacturing/Distribution-Related Employment within 1 Mile:	910
Existing Students:	0
Upload Map	1466004290765_CSAH 081 (Broadway Ave) Bridge - Regional Economy.pdf

Measure C: Current Daily Heavy Commercial Traffic

Location	CSAH 81 north of Lowry Avenue bridge
Current Daily Heavy Commercial Traffic Volume	1113.0
Date Heavy Commercial Count Taken:	10/21/2014

Measure D: Freight Elements

The CSAH 81 bridges over Lowry Avenue/Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway is a regionally significant truck route, carrying 1,113 heavy commercial vehicles each day. Traffic trends show an increase in freight and delivery trucks along this corridor and others in the region.

The CSAH 81 northbound and southbound bridges are both classified as structurally deficient with sufficiency ratings below 50. As these bridges continue to deteriorate, both of these bridges will eventually be closed to heavy commercial vehicles, which may occur in the near future. As it stands, the southbound bridge is already load posted.

As the needs for freight continue to increase along this corridor, this project will improve the mobility, safety and overall operations for truck traffic. The proposed replacement of the CSAH 81 bridges will support the economic development in the area by providing smooth and efficient traffic flow, by providing access to key destinations along the corridor. The bridge replacement project will eliminate all weight restrictions on this segment of CSAH 81 to continue to provide a regional facility for freight traffic. In addition, the typical roadway section will be widened with this project to better accommodate freight traffic. The project will widen each shoulder from three to four feet to meet current standards.

Measure A: Current Daily Person Throughput

Location	CSAH 81 Bridges
Current AADT Volume	12100.0
Existing Transit Routes on the Project:	14, 19, 32
Upload Transit Map	1466526715540_CSAH 081 (Broadway Ave) Bridge - Transit.pdf

Response (Limit 1,400 characters; approximately 200 words)

Response: Curren	t Daily Person	Throughput
-------------------------	----------------	------------

Average Annual Daily Transit Ridership	0
Current Daily Person Throughput	15730.0

Measure B: 2040 Forecast ADT

Yes
0
No
24700.0

Measure A: Project Location and Impact to Disadvantaged Populations

Select one:

Project located in Area of Concentrated Poverty with 50% or more of residents are people of color (ACP50):

Project located in Area of Concentrated Poverty:

Projects census tracts are above the regional average for population in poverty or population of color:

Project located in a census tract that is below the regional average for population in poverty or populations of color or includes children, people with disabilities, or the elderly:

The CSAH 81 Bridge is located within an Area of Concentrated Poverty (ACP). According to census data collected over a span of five years, 40% of the residents within the ACP live with incomes below 185% of the federal poverty threshold. Within this ACP, 50% or more of the population are people of color.

Research shows that residents of ACP are three times more likely to lack a high school diploma or GED (differences at higher education levels are less pronounced). Data also indicates a larger immigrant (born outside of the US) presence and a greater share of residents speaking a language other than English at home within ACP areas.

Within and beyond the ACP boundaries at CSAH 81, are neighborhoods that were greatly impacted by the recession of the late 2000's and the associated foreclosure crisis, as well as a tornado in 2011. These neighborhoods are struggling to compete with other surrounding neighborhoods for rare redevelopment opportunities that will bring jobs, quality affordable housing, retail and services to their neighborhood.

In an effort to stabilize these economically challenged neighborhoods, Hennepin County reconstructed a 2.5 mile stretch of Lowry Avenue through North Minneapolis with on-street bicycle lanes, landscaped boulevards, and wider sidewalks between 2006 and 2009. Hennepin County is also currently working to redevelop two key intersections along the corridor. Lowry Avenue travels under the CSAH 81 bridge structure and has entrance ramps that provide access onto CSAH 81.

Response (Limit 2,800 characters; approximately 400 words)

corridor, providing a vital connection to the metropolitan freeway system which ultimately connects residents (inclusive of all races, ethnicity, incomes, and abilities) to jobs and educational opportunities. The replacement of the CSAH 81 bridges is consistent with the goals and desired outcomes in Thrive 2040 and will continue to connect local residents with a safe and reliable transportation system to improve their overall quality of life.

The response should address the benefits, impacts, and mitigation for the populations affected by the project.

Up	load	Map	

1466096913109_CSAH 081 (Broadway Ave) Bridge - SocioEconomic.pdf

Measure B: Affordable Housing

City/Township	Segment Length in Miles (Population)
Minneapolis	22012.0
Robbinsdale	8657.0
Golden Valley	4637.0
	35306
Total Project Lengt	h

Total Project Length (Total Population)	0.15
	0.1

Affordable Housing Scoring - To Be Completed By Metropolitan Council Staff

City/Township	Segment Length (Miles)	Total Length (Miles)	Score	Segment Length/Total Length	Housing Score Multiplied by Segment percent
Minneapolis	0.02	35306.0	97.0	0	0
Robbinsdale	0.06	35306.0	61.0	0	0
Item Deleted	0	35306.0	0	0	0
		105918	158	0	0

Affordable Housing Scoring - To Be Completed By Metropolitan Council Staff

Total Project Length (Miles)	35306.0
Total Housing Score	0
Measure A: Bridge Condition	
Bridge Sufficiency Rating	24.9
Measure B: Project Improvements	
Load Posted (Check box if the bridge is load-posted):	Yes

Measure A: Multimodal Elements and Existing Connections

Today, the CSAH 81 bridges include two travel lanes in each direction, connecting traffic between Robbinsdale and the northwest metro to Minneapolis. Dedicated pedestrian and bicycle routes do not currently exist on the bridges. Instead, people walking or biking are routed below the bridge on a network of sidewalks and multi-use paths including the Grand Rounds Trail. By traveling below the bridge, pedestrians and bicyclists are able to stay at grade and connect directly into the renowned regional trail system and local sidewalk network. Lowry Avenue, located below the bridge, is served by transit routes 14, 19, and 32, and additionally includes on-street bike lanes east of CSAH 81.

While existing sidewalks, bike lanes, and trails provide reasonably direct connections for nonmotorized users, there is an opportunity to increase connectivity and provide an even more direct route with the addition of dedicated pedestrian and bicycle facilities on the bridge. The reconstructed CSAH 81 bridges will include multi-use trail facilities adjacent to outside vehicle travel lanes. Further study will be completed to evaluate how to best connect new facilities with the existing network pedestrian and bicycle network. In the interim, there is an opportunity to maximize use and awareness of existing sidewalk and trail connections by enhancing wayfinding north and south of the project area.

Additional concurrent and upcoming multimodal projects will further enhance the role of this location in the pedestrian, bicycle, and transit system. The Crystal Lake Regional Trail, currently in late planning and early implementation stages, will provide a new bikeway and improved pedestrian route through Maple Grove, Brooklyn Park, Crystal,

Response (Limit 2,800 characters; approximately 400 words)

and Robbinsdale, connecting to the Grand Rounds Trail on the north side of the CSAH 81 bridge project. CSAH 81 is also recognized as an exploration corridor for future BRT expansion, which would elevate the corridor's importance in the regional transit network.

Transit Projects Not Requiring Construction

If the applicant is completing a transit or TDM application that is operations only, check the box and do not complete the remainder of the form. These projects will receive full points for the Risk Assessment.

Park-and-Ride and other transit construction projects require completion of the Risk Assessment below.

Check Here if Your Transit Project Does Not Require Construction

Measure A: Risk Assessment

1)Project Scope (5 Percent of Points)	
Meetings or contacts with stakeholders have occurred	Yes
100%	
Stakeholders have been identified	
40%	
Stakeholders have not been identified or contacted	
0%	
2)Layout or Preliminary Plan (5 Percent of Points)	
Layout or Preliminary Plan completed	
100%	
Layout or Preliminary Plan started	
50%	
Layout or Preliminary Plan has not been started	Yes
0%	
Anticipated date or date of completion	06/30/2020
3)Environmental Documentation (5 Percent of Points)	
EIS	
EA	
PM	Yes
Document Status:	
Document approved (include copy of signed cover sheet)	100%

	75%
Document in progress; environmental impacts identified; review request letters sent	
50%	
Document not started	Yes
0%	
Anticipated date or date of completion/approval	08/31/2020
4)Review of Section 106 Historic Resources (10 Percent of	Points)
No known historic properties eligible for or listed in the National Register of Historic Places are located in the project area, and project is not located on an identified historic bridge 100%	Yes
Historic/archeological review under way; determination of no historic properties affected or no adverse effect anticipated	
80%	
Historic/archaeological review under way; determination of adverse effect anticipated	
40%	
Unsure if there are any historic/archaeological resources in the project area	
0%	
Anticipated date or date of completion of historic/archeological review:	
Project is located on an identified historic bridge	
5)Review of Section 4f/6f Resources (10 Percent of Points)	
4(f) Does the project impacts any public parks, public wildlife refuges, public golf courses, wild & scenic rivers or public private historic proper 6(f) Does the project impact any public parks, public wildlife refuges, public golf courses, wild & scenic rivers or historic property that was purchased or improved with federal funds?	ties?
No Section 4f/6f resources located in the project area	
100%	
No impact to 4f property. The project is an independent bikeway/walkway project covered by the bikeway/walkway Negative Declaration statement; letter of support received 100%	
Section 4f resources present within the project area, but no known adverse effects	Yes
80%	

date submitted

Project impacts to Section 4f/6f resources likely coordination/documentation has begun

Document submitted to State Aid for review

50%

Project impacts to Section 4f/6f resources likely coordination/documentation has not begun 30% Unsure if there are any impacts to Section 4f/6f resources in the project area 0% 6)Right-of-Way (15 Percent of Points) Right-of-way, permanent or temporary easements not required Yes 100% Right-of-way, permanent or temporary easements has/have been acquired 100% Right-of-way, permanent or temporary easements required, offers made 75% Right-of-way, permanent or temporary easements required, appraisals made 50% Right-of-way, permanent or temporary easements required, parcels identified 25% Right-of-way, permanent or temporary easements required, parcels not identified 0% Right-of-way, permanent or temporary easements identification has not been completed 0% Anticipated date or date of acquisition 7) Railroad Involvement (25 Percent of Points) No railroad involvement on project Yes 100% Railroad Right-of-Way Agreement is executed (include signature page) 100% Railroad Right-of-Way Agreement required; Agreement has been initiated 60% Railroad Right-of-Way Agreement required; negotiations have begun 40% Railroad Right-of-Way Agreement required; negotiations not begun 0%

Anticipated date or date of executed Agreement	
8)Interchange Approval (15 Percent of Points)*	
*Please contact Karen Scheffing at MnDOT (Karen.Scheffing@state.rr to determine if your project needs to go through the Metropolitan Cour Interchange Request Committee.	
Project does not involve construction of a new/expanded interchange or new interchange ramps	Yes
100%	
Interchange project has been approved by the Metropolitan Council/MnDOT Highway Interchange Request Committee	
100%	
Interchange project has not been approved by the Metropolitan Council/MnDOT Highway Interchange Request Committee	
0%	
9)Construction Documents/Plan (10 Percent of Points)	
Construction plans completed/approved (include signed title sheet)	
100%	
Construction plans submitted to State Aid for review	
75%	
Construction plans in progress; at least 30% completion	
50%	
Construction plans have not been started	Yes
0%	
Anticipated date or date of completion	12/31/2020
10)Letting	
Anticipated Letting Date	04/15/2021


Measure A: Cost Effectiveness


Total Project Cost (entered in Project Cost Form):	\$13,500,000.00
Enter Amount of the Noise Walls:	\$0.00
Total Project Cost subtract the amount of the noise walls:	\$13,500,000.00
Points Awarded in Previous Criteria	
Cost Effectiveness	\$0.00


Other Attachments

File Name	Description	File Size
Fig 01 - Project Map_CSAH 081Bridges.pdf	Project Map_CSAH 081Bridges	436 KB
Fig 02 - MnDOT Bridge Inspection and Inventory Reports - CSAH 81 NB.pdf	MnDOT Bridge Inspection and Inventory Reports - CSAH 81 NB	99 KB
Fig 03 - MnDOT Bridge Inspection and Inventory Reports - CSAH 81 SB.pdf	MnDOT Bridge Inspection and Inventory Reports - CSAH 81 SB	97 KB
Fig 04 - CSAH 81 Bridge - Existing Typical Section.pdf	CSAH 81 Bridge - Existing Typical Section	158 KB
Fig 05 - CSAH 81 Bridge - Proposed Typical Section.pdf	CSAH 81 Bridge - Proposed Typical Section	213 KB
Fig 06 - Photos of CSAH 81 Bridge Deficiencies.pdf	Photos of CSAH 81 Bridge Deficiencies	716 KB
Fig 07 - CSAH 81 Bridge Heavy Commercial Traffic.pdf	CSAH 81 Bridge Heavy Commercial Traffic	74 KB
Fig 08 - CSAH 081 - 2016 Traffic Volumes.pdf	CSAH 081 - 2016 Traffic Volumes	61 KB
Fig 09 - CSAH 81 Bridge 2040 Forecasts from Mark Filipi.pdf	CSAH 81 Bridge 2040 Forecasts from Mark Filipi	96 KB
Fig 10 - Minneapolis Plan for Sustainable Growth Regional Parks and Trails.pdf	Minneapolis Plan for Sustainable Growth Regional Parks and Trails	407 KB
Fig 11 - Access Minneapolis CitywideActionPlan Transit Oriented Commercial Corridors.pdf	Access Minneapolis CitywideActionPlan Transit Oriented Commercial Corridors	1.2 MB
Fig 12 - GrandRoundsMasterPlan_Map.pdf	Grand Rounds Master Plan Map	77 KB
Fig 13 - Crystal Lake Regional Trail Assessment - Robbinsdale Segment.pdf	Crystal Lake Regional Trail Assessment - Robbinsdale Segment	591 KB
Fig 14 - WestBroadway_RapidBusConcept.pdf	WestBroadway_RapidBusConcept	228 KB
Fig 15 - HCBikePlan_Top25PlannedBikewaySeg ments.pdf	HC Bike Plan Top25 Planned Bikeway Segments	873 KB
Fig 16 - RobbinsdalePedBikePlan - PriorityIntersections.pdf	Robbinsdale Ped Bike Plan - Priority Intersections	281 KB
Fig 17 - RobbinsdalePedBikePlan - Recommended Network.pdf	Robbinsdale Ped Bike Plan - Recommended Network	280 KB
Fig 18 - Robbinsdale Support Letter.pdf	Robbinsdale Support Letter	47 KB
Fig 19 - Minneapolis Support Letter.pdf	Minneapolis Support Letter	238 KB









CSAH 81 (W Broadway Ave/Bottineau Blvd) - Bridge Replacement Project

Figure 01 - Project Location Map

Hennepin Hennepin 07/11/2016



Page 1 of 7

MINNESOTA STRUCTURE INVENTORY REPORT

Bridge ID: 27008

CSAH 81 NB over MSAS 295; STR 184

Date: 06/10/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +
Agency Br. No.	Bridge Match ID (TIS) 1	Deficient Status S.D.
District METRO Maint. Area	Roadway O/U Key 1-ON	Sufficiency Rating 44.2
County 27 - HENNEPIN	Route Sys/Nbr CSAH 81	Last Inspection Date 08-25-2015
City ROBBINSDALE	Roadway Name or Description	Inspection Frequency 12
Township	CSAH 81 (BROADWAY) NB	Inspector Name HENNEPIN COUNTY
Desc. Loc. 2.3 MI NW OF JCT TH 94	Roadway Function MAINLINE	Status A-OPEN
Sect., Twp., Range 08 - 029N - 24W	Roadway Type 1 WAY TRAF	+ NBI CONDITION RATINGS +
Latitude 45d 00m 49.36s	Control Section (TH Only)	Deck 5
Longitude 93d 19m 07.33s	Ref. Point 002+00.310	Superstructure 4
Custodian COUNTY	Date Opened to Traffic 01-01-1964	Substructure 5
Owner COUNTY	Detour Length 1 mi.	Channel N
Inspection By HENNEPIN COUNTY	Lanes 2 Lanes ON Bridge	Culvert N
Year Built 1964	ADT (YEAR) 6,250 (2005)	+ NBI APPRAISAL RATINGS
MN Year Remodeled	HCADT	Structure Evaluation 4
FHWA Year Reconstructed	Functional Class. URB/MINOR ART	Deck Geometry 4
Bridge Plan Location COUNTY	+ RDWY DIMENSIONS +	Underclearances 2
Potential ABC N.A.	If Divided NB-EB SB-WB	Waterway Adequacy N
	Roadway Width 30.0 ft	Approach Alignment 8
+ STRUCTURE +	Vertical Clearance	+ SAFETY FEATURES +
Service On HIGHWAY	Max. Vert. Clear.	Bridge Railing 1-MEETS STANDARDS
Service Under HIGHWAY	Horizontal Clear. 29.9 ft	GR Transition 1-MEETS STANDARDS
Main Span Type CCONC BOX GIRD	Lateral Cir Lt/Rt	Appr. Guardrail 1-MEETS STANDARDS
Main Span Detail	Appr. Surface Width 30.0 ft	GR Termini 1-MEETS STANDARDS
Appr. Span Type	Bridge Roadway Width 30.0 ft	+ IN DEPTH INSP. +
Appr. Span Detail	Median Width on Bridge	Frac. Critical
Skew 45R	+ MISC. BRIDGE DATA +	Underwater
Culvert Type	Structure Flared NO	Pinned Asbly.
Barrel Length	Parallel Structure RIGHT	Spec. Feat.
Number of Spans	Field Conn. ID	+ WATERWAY +
MAIN: 4 APPR: 0 TOTAL: 4	Cantilever ID	Drainage Area
Main Span Length 121.6 ft	Foundations	Waterway Opening
Structure Length 426.7 ft	Abut. CONC - FTG PILE	Navigation Control NOT APPL
Deck Width 35.5 ft	Pier CONC - FTG PILE	Pier Protection
Deck Material C-I-P CONCRETE	Historic Status NOT ELIGIBLE	Nav. Vert./Horz. Cir.
Wear Surf Type LOW SLUMP CONC	On - Off System ON	Nav. Vert. Lift Bridge Clear.
	+ PAINT +	MN Scour Code A-NON WATERWAY
Wear Surf Install Year 1978 Wear Course/Fill Depth 0.17 ft	Year Painted Pct. Unsound	Scour Evaluation Year 1991
Deck Membrane NONE	Painted Area	+ CAPACITY RATINGS +
Deck Rebars NONE	Primer Type	Design Load HS 20 Operating Rating HS 26.40
Deck Rebars Install Year	Finish Type	
Structure Area 15,148 sq ft	+ BRIDGE SIGNS +	Inventory Rating HS 15.80
Roadway Area 12,798 sq ft	Posted Load NOT REQUIRED	Posting
Sidewalk Width - L/R 1.0 ft 1.0 ft	Traffic NOT REQUIRED	Rating Date 02-03-2015
Curb Height - L/R 0.67 ft 0.67 ft	Horizontal OBJECT MARKERS	Overweight Permit Codes
Rail Codes - L/R 29 29	Vertical NOT APPLICABLE	A: N B: N C: N

BRIDGE INVENTORY SUB REPORT.RPT

6/10/2									
	010	Μ		IDGE INS		REPORT			
•	ed by: HE 3E 2700		ER MSAS 295; STR	184			P. DATE: 08	25 2015	
County City: Fownsl Sectior	/: HENNE ROBBINS hip: n: 08 Towi	PIN	-	NW OF JCT T Ref. Pt.: Main	H 94 002+00.310 t. Area:	Length: 42 Deck Width: Rdwy. Area	26.7 ft : 35.5 ft / Pct. Unsnd: Pct. Unsnd:	12,798 sc	l ft
Apprais	sal Rating	Super: 4 Sub: 5 Chan: N (s - Approach: 8 Waterway: N Signs - Load Posting: NOT RE Horizontal: OBJECT M	Upo I MN EQUIRED Traffic: NO	en, Posted, Cl Scour Code: DT REQUIRE NOT APPLICA	A-NON WATEF D	RWAY D	ef. Stat: S.D.	Suff. Rate	<u>:</u> 44.2
ELE NB		ELEMENT NAME	INSP.	DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
800		CAL DEFS OR SAFETY HAZA			1 EA	1	0	0	0
	Notes:	No critical structural deficienc	ies or serious safety ha	zards are pres	sent on this structu	re.			
16	REINF	ORCED CONCRETE TOP FL	ANGE 08-25-	2015	15,148 SF	14,845	0	303	C
510	Notes: 0 WEARI Notes:	359. Efflor, much scaling and both cantilevers. '13-many sp edge NG SURFACE Low Slump Overlay with Unit scaled @ E side(50' X 5' are	alls on cantilevers. '14-r 08-25- coated Rebar Notes: 22	no change. '15 2015 . <i>Trans, long a</i>	5-51SF of spalling v 12,798 SF and some map crac	vith rebar alor 11,518 cks. Wear cou	ng W edge, 58S 0 arse sealed in '0	F along E 1,280 5. <i>Surface</i>	(
		of right lane. Some small sp	alls. most @ strip seal id						
10	CONC	of right lane. Some small sp patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE	n left lane @ poured joi and width x 6", sunken a been sealed as well	pints. Numerou s in N span, s nt over middle area of middle	us unsealed long, t ome sealed. '13-cr column is cracked	rans and map acks are gene I & sunken 3/8	o cracks. Few sr erally larger in si 3" - 1/2". '15-Lef	nall ize, some ft lane @	(
310	CONC Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full k remaining deck cracks have	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some	us unsealed long, t ome sealed. '13-cm column is cracked column has been 0 LF de sealed. Most cra e cracks now 1/32"	rans and map acks are gene I & sunken 3/8 repaired with p 0 cks in right lau	o cracks. Few sr erally larger in si 3" - 1/2". '15-Lef patch and seala 0 0 ne, where tine s	mall ize, some it lane @ int, 0 surface is	
	Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some s have been s	us unsealed long, t ome sealed. '13-cm column is cracked column has been 0 LF de sealed. Most cra e cracks now 1/32"	rans and map acks are gene I & sunken 3/8 repaired with p 0 cks in right lau	o cracks. Few sr erally larger in si 3" - 1/2". '15-Lef patch and seala 0 0 ne, where tine s	mall ize, some it lane @ int, 0 surface is	
	Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. '	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N jo repaired areas. 4' parti	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some s have been s 2015 2015	us unsealed long, t ome sealed. '13-cm o column is cracked column has been i 0 LF de sealed. Most cra e cracks now 1/32" sealed 72 LF points almost closed	rans and map acks are gene I & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa	o cracks. Few sr erally larger in si 3" - 1/2". '15-Lef batch and seala 0 ne, where tine s 1 '13-some crac 43 me in '12. '12-n	mall ize, some it lane @ ont, 0 surface is sks up to +/ 0 uumerous	
300	Notes: STRIP Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N jo repaired areas. 4' parti	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Some end. '12-some s have been s 2015 bint. '11-both ja ally out in S; 3	us unsealed long, t ome sealed. '13-cm o column is cracked column has been i 0 LF de sealed. Most cra e cracks now 1/32" sealed 72 LF points almost closed	rans and map acks are gene I & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa	o cracks. Few sr erally larger in si 3" - 1/2". '15-Lef batch and seala 0 ne, where tine s 1 '13-some crac 43 me in '12. '12-n	mall ize, some it lane @ ont, 0 surface is sks up to +/ 0 uumerous	(
300	Notes: STRIP Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in about 8'. '14-no change. '15-r	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N jo repaired areas. 4' parti- to change 08-25-	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some 2015 bint. '11-both jo ally out in S; 3 2015	us unsealed long, t ome sealed. '13-cr column is cracked o LF 0 LF te sealed. Most cra e cracks now 1/32" sealed 72 LF bints almost closed ' in N. '13-85 degre 325 LF	rans and map acks are gene & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa ces, N joint is 305	o cracks. Few sr prally larger in su 3" - 1/2". '15-Lef patch and seala 0 ne, where tine s . '13-some crac 43 ume in '12. '12-n closed in the mi	mall ize, some it lane @ ont, 0 surface is sks up to +/ 0 numerous iddle for 0	(
300	Notes: STRIP Notes: POURI Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area if app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in about 8'. '14-no change. '15-r ED SEAL JOINT 301. Material partially missing	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N jo repaired areas. 4' parti- to change 08-25-	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some shave been s 2015 bint. '11-both ja 2015 2015 ne cracks in m	us unsealed long, t ome sealed. '13-cr column is cracked o LF 0 LF te sealed. Most cra e cracks now 1/32" sealed 72 LF bints almost closed ' in N. '13-85 degre 325 LF	rans and map acks are gene & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa ces, N joint is 305	o cracks. Few sr erally larger in su 3" - 1/2". '15-Lef batch and seala 0 ne, where tine s . '13-some crac 43 ume in '12. '12-n closed in the mi	mall ize, some it lane @ ont, 0 surface is sks up to +/ 0 numerous iddle for 0	(
300 301	Notes: STRIP Notes: POURI Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in about 8'. '14-no change. '15-r ED SEAL JOINT 301. Material partially missing change. '15-no change	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N jo repaired areas. 4' parti- to change 08-25- g in some areas. '13-sor 08-25-	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Some end. '12-some s have been s 2015 bint. '11-both ju ally out in S; 3 2015 ne cracks in m 2015	us unsealed long, t ome sealed. '13-cm column is cracked column has been in 0 LF the sealed. Most cracked cracks now 1/32" sealed 72 LF toints almost closed 'i in N. '13-85 degree 325 LF thaterial. Deck spall 69 LF	rans and map acks are gene & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa ees, N joint is 305 @ middle brid 0	o cracks. Few sr erally larger in su 3" - 1/2". '15-Lef batch and seala 0 ne, where tine s '. '13-some crac 43 ame in '12. '12-n closed in the mi 15 dge joint. '14-no 29	mall ize, some it lane @ ont, 0 surface is surface is sks up to +/ 0 uumerous iddle for 0	(((
300 301 302	Notes: STRIP Notes: POUR Notes: COMP Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in about 8'. '14-no change. '15-r ED SEAL JOINT 301. Material partially missing change. '15-no change RESSION DECK JOINT 302. Joints @ end of bridge.	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N join repaired areas. 4' parti- no change 08-25- g in some areas. '13-som 08-25- d in some areas. '13-som	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Som end. '12-some shave been s 2015 bint. '11-both ja 2015 ne cracks in m 2015 deteriorated.	us unsealed long, t ome sealed. '13-cm column is cracked column has been in 0 LF the sealed. Most cracked cracks now 1/32" sealed 72 LF toints almost closed 'i in N. '13-85 degree 325 LF thaterial. Deck spall 69 LF	rans and map acks are gene & sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 @ 70 deg-sa ees, N joint is 305 @ middle brid 0	o cracks. Few sr erally larger in su 3" - 1/2". '15-Lef batch and seala 0 ne, where tine s '. '13-some crac 43 ame in '12. '12-n closed in the mi 15 dge joint. '14-no 29	mall ize, some it lane @ ont, 0 surface is surface is sks up to +/ 0 uumerous iddle for 0	
810 300 301 302 331	Notes: STRIP Notes: POUR Notes: COMP Notes:	patches, up to 2' x 4' in size. up to 1/16". '14-8" x 3' area i app has been patched, full la remaining deck cracks have WEAR SURF-CRACKING SE 358. Numerous trans, long ar wore. Most of the cracking in - 1/16" in size. Density <10'. ' SEAL DECK JOINT 300. Joints partially filled w/ s spalls @ S joint in adj conc in about 8'. '14-no change. '15-r ED SEAL JOINT 301. Material partially missing change. '15-no change RESSION DECK JOINT 302. Joints @ end of bridge. both. '15-no change	Numerous larger crack in left lane @ poured join and width x 6", sunken a been sealed as well ALING 08-25- nd map cracks. Minor in the left lane is @ the N 14-no change. '15-crack 08-25- and. 1' X 1' spall @ N join repaired areas. 4' parti- no change 08-25- g in some areas. '13-som 08-25- d in some areas. '13-som 08-25- no change	bints. Numerou s in N span, s nt over middle area of middle 2015 severity. Some end. '12-some s have been s 2015 bint. '11-both ju ally out in S; 3 2015 ne cracks in m 2015 deteriorated. 2015 reral joints. Sp e scale. Crack	us unsealed long, t ome sealed. '13-cr column is cracked column has been i 0 LF de sealed. Most cra e cracks now 1/32" sealed 72 LF bints almost closed '1 in N. '13-85 degre 325 LF daterial. Deck spall 69 LF '13-small spalls @ 853 LF eall w/ rebar exp @ ked and spalled ne	rans and map acks are gene (& sunken 3/8 repaired with p 0 cks in right lan ; density < 10' 29 (@ 70 deg-sa ces, N joint is 305 (@ middle brid 0 joint in N. '14 0 SE endpost. 1 ar the top in S	o cracks. Few sr parally larger in su arrally larger in su arrally larger in su arrally larger in su arrange in su 0 ne, where time su 43 arrange in '12. '12-n closed in the mi 15 dge joint. '14-no 29 -more deteriora 799 Rust stains @ E SE. '13-many po	mall ize, some it lane @ int, 0 surface is sks up to +/ 0 numerous iddle for 0 0 0 tion @ 54 E wall. ists w/	

	Notes:	407. Spalls on both ends. Approach			-		-	Page 3 of
		ponding in SW corner. Settled on N Large crack in middle of S. '14-S ap			eteriorated. 13-i	arge spails in	IN.	
105	REINF	ORCED CONCRETE BOX GIRDER		427 LF	0	262	162	3
	Notes:	105. Numerous vert cracks on side cracks @ bottom of girder of all spa deflection apparent-minor. Spalls w sides. Repaired W side hinge joint rebar on W side. Spalls & delam in hinge. 1 SF delam over N abut betw less on S half of these spans. 2nd s S 2/3 of span. Minor-mod shear cra deterioration @ hinges. '14-2 W be-	ans. Bottom of girders scraped // rebar exp in W face of spans cracks and spall in '01 and '04 bottom of girder @ N joint. '13 ween 2 W bearings. Trans crac span from S has same density acking on both sides of girder.	. Girders spalled, some a 1 & 2. Repaired areas . 3 SF patch on E side. -repaired areas are spa cks spaced 2'-3' apart in from hinge to 20' S of	w/ rebar exp @ in span 1 are s Some spalling, alling again. 60 n N half of 2 N s column 2. S spa	hinges. Long palled on E and delam and ru SF of spalls (spans. Density an density is 2	g term nd W isted ⊉ N y is ''-3' in	
205	REINF	ORCED CONCRETE COLUMN	08-25-2015	3 EA	3	0	0	0
	Notes:	205. Hairline vert cracks. Map crack '15-very few coin sized popouts on		s are minor in size. '14	-scrapes @ bas	e of S columr	۱.	
215	REINF	ORCED CONCRETE ABUTMENT	08-25-2015	119 LF	30	65	24	0
	Notes:	[2016] Migrator added 40 LF to abu 215. Horiz and vert cracks in both. spalled @ SW corner. 1.5' X 2' X 2' parapet wall @ S where electrical of Spalls & leakage @ blockouts. Nor parapet wall spalled @ joint. NW se S face, 1.5'x2'x3", 1.5'x3'x2" and 1' Wingwall patter: 287. Heria and war	Rust @ seats & faces. Leakag ' deep spall w/ rebar exp @ ce conduit exits. '13-spall on face th-parapet wall cracked and sp eat has 4' X 1' delam. '13-delar x1'. Spall in NW seat has been	e from utility blockout in enter on face and seat. and seat is now 3" dee balled @ NW corner. 2' m in NW is now a spall. n repaired	n parapet @ bo Small spall in S p. Leakage @ c X 2' X 5" deep . '14-no change	th. South- ma E seat. Leaka conduit is heav spall @ NW s '15-3 spalls a	age thru vy. seat. NE along	
311		Wingwall notes: 387. Horiz and ver NSION BEARING	t cracks w/ efflor in NW. Large 08-25-2015	spall in SE. '13-no cha 20 EA	inge. '14-same. 0	15-no change 6	e0	14
	Notes:	311. Exterior bearings rusted @ str exterior corner of box cracking. Sur lower bearing assemblies @ N. Litt Interior hinge bearings appear OK.	face rust on rest of bearings. ' le if any movement @ many al	13-N abut bearings hav but bearings. Ext bearii	ve some sheet r ng seats of both	ust. Mod rust hinges spalle	on all ed.	
		change						
851	CONC	change RETE HINGE ASSEMBLY	08-25-2015	2 EA	0	0	1	1
351	CONC Notes:	•	palls @ W side of N hinge-6' X I @ all hinges in '04. Some birg ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g I5-N half of N hinge has	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork	ar exp @ both y spalled and rebar. Bird sci / section loss remaining, tot	part reens of exp tal	1
351	Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last insp rebar. 2 W bearing seats @ N hing spall area is 28SF on N half & 17SF	palls @ W side of N hinge-6' X I @ all hinges in '04. Some birg ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g I5-N half of N hinge has	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork	ar exp @ both y spalled and rebar. Bird sci / section loss remaining, tot	part reens of exp tal	1
	Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last inspir rebar. 2 W bearing seats @ N hing spall area is 28SF on N half & 17SF of girder	palls @ W side of N hinge-6' X I @ all hinges in '04. Some bird ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1 F in W corner. Majority of patc 08-25-2015	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g I5-N half of N hinge has shwork on S joint is in ta	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork act, majority of s	ar exp @ both ly spalled and rebar. Bird sca / section loss remaining, tot spalls along W 0	part reens of exp tal / edge 1	0
383	Notes: CONC Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last inspirebar. 2 W bearing seats @ N hing spall area is 28SF on N half & 17SF of girder RETE SHEAR CRACKING 965. '13-element added. Shear crac	palls @ W side of N hinge-6' X I @ all hinges in '04. Some bird ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1 F in W corner. Majority of patc 08-25-2015	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g I5-N half of N hinge has shwork on S joint is in ta	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork act, majority of s	ar exp @ both ly spalled and rebar. Bird sca / section loss remaining, tot spalls along W 0	part reens of exp tal / edge 1	0
	Notes: CONC Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last inspirebar. 2 W bearing seats @ N hing spall area is 28SF on N half & 17SF of girder RETE SHEAR CRACKING 965. '13-element added. Shear crac '14-no change. '15-no change	palls @ W side of N hinge-6' X d @ all hinges in '04. Some bird ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1 = in W corner. Majority of patc 08-25-2015 cks in many areas of girders. N 08-25-2015 08-25-2015	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g 15-N half of N hinge has shwork on S joint is in ta 1 EA Most are minor but som 1 EA	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork act, majority of s 0 e are moderate 0 s. '13-missing X	ar exp @ both y spalled and rebar. Bird sci / section loss remaining, tot spalls along W 0 in size(<1/32 0 4-4 in SW. '14	l part reens of exp tal / edge 1 "). 1 4-X4-4	-
383	Notes: CONC Notes: OTHEI Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last inspirebar. 2 W bearing seats @ N hingu- spall area is 28SF on N half & 17SF of girder RETE SHEAR CRACKING 965. '13-element added. Shear crace '14-no change. '15-no change R BRIDGE SIGNING 981. Horiz clearance marker X4-4 (in SW has been replaced. Merge si	palls @ W side of N hinge-6' X d @ all hinges in '04. Some bird ed @ W side. '13-S joint spalle ection. '14-most patches @ N e have cracks w/ rust stains. '1 = in W corner. Majority of patc 08-25-2015 cks in many areas of girders. N 08-25-2015 08-25-2015	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g 15-N half of N hinge has shwork on S joint is in ta 1 EA Most are minor but som 1 EA	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork act, majority of s 0 e are moderate 0 s. '13-missing X	ar exp @ both y spalled and rebar. Bird sci / section loss remaining, tot spalls along W 0 in size(<1/32 0 4-4 in SW. '14	l part reens of exp tal / edge 1 "). 1 4-X4-4	-
383	Notes: CONC Notes: OTHEI Notes:	RETE HINGE ASSEMBLY 379. Repaired severe cracks and s Expanded metal bird screen placed of bird screen is gone. S joint spalle have been removed since last inspe- rebar. 2 W bearing seats @ N hing- spall area is 28SF on N half & 17SF of girder RETE SHEAR CRACKING 965. '13-element added. Shear crace '14-no change. '15-no change R BRIDGE SIGNING 981. Horiz clearance marker X4-4 (in SW has been replaced. Merge si change	palls @ W side of N hinge-6' X d @ all hinges in '04. Some bird ed @ W side. '13-S joint spalle ection. '14-most patches @ N is e have cracks w/ rust stains. '1 = in W corner. Majority of patc 08-25-2015 cks in many areas of girders. N 08-25-2015 @ SE approach. Plow up/dowr ign in NE. Keep Right missing 08-25-2015 Some slope paving cracked. Jo Small spall @ bottom of S slo	(3' X 3" in '01 and '04. d screen loose from gir d on both sides. Some are spalled off. 5" x 3' g I5-N half of N hinge has thwork on S joint is in ta 1 EA Most are minor but som 1 EA n X4-5 @ S approaches @ median nose for NB 1 EA n EA	Spalling w/ reba der. N joint bad section loss of gone @ edge w s no patchwork act, majority of s 0 e are moderate 0 s. '13-missing X Victory Memor 0 4-new joint seal WW corner. '11-	ar exp @ both ly spalled and rebar. Bird sca l' section loss remaining, tot spalls along W 0 in size(<1/32 0 4-4 in SW. '14 ial Drive. '15-r 0 @ abut slope 20' of joint sea	part reens of exp tal / edge 1 "). 1 4-X4-4 no 0 s al loose	0

Page 4 of 7

	Notes:	982. Guardrail in place @ S corners '14-spacer block missing in SE. '15-'	-	Rail not attached to s	everal posts in	SW. '13-no cł		Page 4 of i
894	DECK	& APPROACH DRAINAGE	08-25-2015	1 EA	0	1	0	0
	Notes:	984. Deck drains are plugged w/ cor so some runoff stays on deck. '13-nd		-	dway @ S end is	s raised above	e deck	
895	SIDE	NALK, CURB, & MEDIAN	08-25-2015	1 EA	0	0	0	1
	Notes:	986. Trans, long and map cracks @ '14-same. '15-cracks in curbline hav		ely spalled w/ rebar ex	kp. Few vert cra	cks. '13-no cł	nange.	
399	MISC	ELLANEOUS ITEMS	08-25-2015	1 EA	1	0	0	0
	Notes:	988. Lights attached to 2 southerly o E rail.	olumns. Light attached to bott	om of girder behind w	alk in S span. '1	4-2 street ligh	nts on	
900	PROT	ECTED SPECIES	08-25-2015	1 EA	1	0	0	0
	General Notes:	*Bridge 27008 NB CSAH 81 (Broadwa	ay Ave)/Victory Mem Dr and Lo	owry Ave. 8/25/15. Wo	JM and JDE.			
		 Patch spalls @ N exp joint. Monitor box girder shear cracks Clean out numerous pigeon drop operations personnel. Repair abut spalls. Monitor strip seals. Seals are viri 301. Replace any missing or deteriora Reseal deck joints @ abut w/ ho Replace broken lateral restraint of 31. Replace spall in SE approach raili Monitor deteriorated hinges. Rep 	ppings inside box girder near h rually closed. ated poured joint material. t pour. @ NW abut bearing. ng.	inge areas. Poses hea	alth risk for insp	ection and		
		407. Replace hot pour material @ S a		cracks in approach.				
		981 Replace horiz clearance marker						

- 981. Replace horiz clearance marker(X4-4) in SW corner.
- 986. Repair curbs in SE & SW.

06/10/2016

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM

Inspected by: HENNEPIN COUNTY

ELEM						QTY	QTY	QTY	QTY	QTY
NBR		ELEMENT NAME	ENV	/ INSP. DATE	QUANTITY	CS 1	CS 2	CS 3	CS 4	CS :
22	LS O/L	(CONC DECK)	3	08-25-2015 08-26-2014	15,145 SF 15,145 SF	0 0	0 0	15,145 15,145	0 0	C
	Notes:	 [22. Trans, long and some map Long cracks over each interior strip seal joints. Numerous uns larger cracks in N span, some @ poured joint over middle col x 6", sunken area of middle col as well 	web wall. Tinec ealed long, tran sealed. '13-crac umn is cracked	I finish is wore of is and map crack iks are generally & sunken 3/8" -	f in wheel tracks of r cs. Few small patche larger in size, some 1/2". '15-Left lane @	ight lane. So es, up to 2' x up to 1/16". app has be	ome small s 4' in size. N '14-8" x 3' en patched	spalls, most (Numerous area in left la , full land wid	@ ane dth	
300	STRIP	SEAL JOINT	3	08-25-2015 08-26-2014	72 LF 72 LF	29 29	43 43	0 0	N/A N/A	N/A N/A
	Notes:	300. Joints partially filled w/ sa '12-numerous spalls @ S joint in the middle for about 8'. '14-n	in adj conc in re	epaired areas. 4'	-	-	-		d	
301	POURE	ED DECK JOINT	3	08-25-2015 08-26-2014	325 LF 325 LF	305 305	15 15	5 5	N/A N/A	N/A N/A
	Notes:	301. Material partially missing change. '15-no change	in some areas.	'13-some cracks	in material. Deck sp	oall @ middle	e bridge joi	nt. '14-no		
302	COMPF	RESSION JOINT	3	08-25-2015 08-26-2014	69 LF 69 LF	0 0	29 29	40 40	N/A N/A	N/A N/A
	Notes:	302. Joints @ end of bridge. ⊢ both. '15-no change	lot pour over joi	nts has deteriora	ted. '13-small spalls	@ joint in N	. '14-more	deterioration	@	
407	BITUMI	NOUS APPROACH	2	08-25-2015 08-26-2014	2 EA 2 EA	0 0	0 0	2 2	0 0	N/A N/A
	Notes:	407. Spalls on both ends. App ponding in SW corner. Settled Large crack in middle of S. '14	on N end w/ mi	nor spalls & som	e cracks. Hot pour h					
331	CONCF	RETE RAILING	3	08-25-2015 08-26-2014	853 LF 853 LF	0 0	799 799	54 54	0 0	N/A N/A
	Notes:	331. Numerous vert cracks in Some map cracking on walls. S vert cracks, some spalled. Sev '15-cracks have been sealed	Surface finish ha	as some scale. C	racked and spalled	near the top	in SE. '13-	many posts v		
105	CONCF	RETE BOX GIRDER	4	08-25-2015 08-26-2014	427 LF 427 LF	0 0	262 262	162 162	3 3	N/A N/A
	Notes:	[105. Numerous vert cracks on cracks @ bottom of girder of al term deflection apparent-minor and W sides. Repaired W side and rusted rebar on W side. Sp spalls @ N hinge. 1 SF delam Density is less on S half of the density is 2'-3' in S 2/3 of span cracks) and 15' from deteriorat & section loss @ N hinge. '15-n Interior inspection of beam A a Good condition inside. 1 small	I spans. Bottom . Spalls w/ reba hinge joint crac palls & delam in over N abut bet se spans. 2nd s . Minor-mod she ion @ hinges. ' no change nd D:	n of girders scrap ir exp in W face of ks and spall in '0 bottom of girder ween 2 W bearin pan from S has s ear cracking on b 14-2 W bearing p	ed. Girders spalled, of spans 1 & 2. Repa 1 and '04. 3 SF pato @ N joint. '13-repai ogs. Trans cracks sp same density from h ooth sides of girder. (edestals @ S abut h	some w/ reb aired areas ir ch on E side. red areas are aced 2'-3' ap inge to 20' S CS 3-150' fro nave cracks.	ar exp @ h span 1 an Some spa e spalling a bart in N ha of column om shear(si 3 LF of spa	hinges. Long e spalled on lling, delam Igain. 60 SF If of 2 N spar 2. S span tructural all w/ rebar e	E of ns. xp	

06/10/2016

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM

Inspected by: HENNEPIN COUNTY **BRIDGE 27008** CSAH 81 NB OVER MSAS 295; STR 184 INSP. DATE: 08-25-2015 ELEM QTY QTY QTY QTY QTY NBR ELEMENT NAME ENV INSP. DATE QUANTITY CS 1 CS 2 CS 3 CS₄ CS 5 CONCRETE HINGE 08-25-2015 0 0 379 4 2 EA 1 1 N/A 08-26-2014 2 EA 0 0 N/A 1 379. Repaired severe cracks and spalls @ W side of N hinge-6' X 3' X 3" in '01 and '04. Spalling w/ rebar exp @ both Notes: hinges. Expanded metal bird screen placed @ all hinges in '04. Some bird screen loose from girder. N joint badly spalled and part of bird screen is gone. S joint spalled @ W side. '13-S joint spalled on both sides. Some section loss of rebar. Bird screens have been removed since last inspection. '14-most patches @ N are spalled off. 5" x 3' gone @ edge w/ section loss of exp rebar. 2 W bearing seats @ N hinge have cracks w/ rust stains. '15-N half of N hinge has no patchwork remaining, total spall area is 28SF on N half & 17SF in W corner. Majority of patchwork on S joint is in tact, majority of spalls along W edge of girder **EXPANSION BEARING** 4 08-25-2015 0 311 20 FA 6 14 N/A N/A 20 EA 6 08-26-2014 0 14 N/A N/A [311. Exterior bearings rusted @ strip seal joints. Bearings @ S abut have some sheet rust. Some abut bearings frozen. Notes: NW exterior corner of box cracking. Surface rust on rest of bearings. '13-N abut bearings have some sheet rust. Mod rust on all lower bearing assemblies @ N. Little if any movement @ many abut bearings. Ext bearing seats of both hinges spalled. Interior hinge bearings appear OK. '14-NW abut bearing has 1 lateral restraint guide broken off of masonry plate. '15-no change 205 CONCRETE COLUMN 4 08-25-2015 3 EA 3 0 0 0 N/A 08-26-2014 3 EA 3 0 0 0 N/A Notes: |205. Hairline vert cracks. Map cracking in pier columns. '13-cracks are minor in size. '14-scrapes @ base of S column. '15-very few coin sized popouts on all columns| 215 CONCRETE ABUTMENT 4 08-25-2015 79 I F 0 55 24 0 N/A 08-26-2014 79 LF 55 24 0 N/A Notes: |215. Horiz and vert cracks in both. Rust @ seats & faces. Leakage from utility blockout in parapet @ both. Southmasonry spalled @ SW corner. 1.5' X 2' X 2" deep spall w/ rebar exp @ center on face and seat. Small spall in SE seat. Leakage thru parapet wall @ S where electrical conduit exits. '13-spall on face and seat is now 3" deep. Leakage @ conduit is heavy. Spalls & leakage @ blockouts. North-parapet wall cracked and spalled @ NW corner. 2' X 2' X 5" deep spall @ NW seat. NE parapet wall spalled @ joint. NW seat has 4' X 1' delam. '13-delam in NW is now a spall. '14-no change. '15-3 spalls along S face, 1.5'x2'x3", 1.5'x3'x2" and 1'x1'. Spall in NW seat has been repaired 387 CONCRETE WINGWALL 4 08-25-2015 4 FA 3 0 0 N/A 1 08-26-2014 4 EA 0 0 3 1 N/A [387. Horiz and vert cracks w/ efflor in NW. Large spall in SE. '13-no change. '14-same. '15-no change] Notes: 358 CONC DECK CRACKING 2 08-25-2015 1 EA 0 0 0 N/A 1 08-26-2014 1 EA 0 0 1 0 N/A Notes: [358. Numerous trans, long and map cracks. Minor in severity. Some sealed. Most cracks in right lane, where tine surface is wore. Most of the cracking in the left lane is @ the N end. '12-some cracks now 1/32"; density < 10'. '13-some cracks up to +/- 1/16" in size. Density <10'. '14-no change. '15-cracks have been sealed| CONC DECK UNDERSIDE 08-25-2015 0 0 0 359 3 1 EA 1 0 08-26-2014 1 FA 0 Ω 0 0 1 359. Efflor, much scaling and rust spots on both cantilevers. Conc pattern cracked @ E cantilever. Spalls w/ rebar exp @ Notes: both cantilevers. '13-many spalls on cantilevers. '14-no change. '15-51SF of spalling with rebar along W edge, 58SF along E edge 964 **CRITICAL FINDING** 2 08-25-2015 1 EA 0 N/A N/A N/A 1 08-26-2014 1 EA 1 0 N/A N/A N/A |964.| Notes: 965 SHEAR CRACKING 2 08-25-2015 1 EA 0 0 0 1 N/A 08-26-2014 1 EA 0 0 1 0 N/A Notes: [965. '13-element added. Shear cracks in many areas of girders. Most are minor but some are moderate in size(<1/32"). '14-no change. '15-no change|

Page 6 of 7

06/10/2016

Inspected by: HENNEPIN COUNTY

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM

BRIDG	SE 2700	8 CSAH 81 NB OVE	R MSAS 295	; STR 184			INSP. DA	TE: 08-25-	2015
ELEM NBR		ELEMENT NAME	EN\	/ INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4
981	SIGNIN	G	2	08-25-2015 08-26-2014	1 EA 1 EA	0 0	0 0	1 1	0 0
	Notes:	 981. Horiz clearance marker X4-4 @ SE approach. Plow up/down X4-5 @ S approaches. '13-missing X4-4 in SW. '14-X4-4 in SW has been replaced. Merge sign in NE. Keep Right missing @ median nose for NB Victory Memorial Drive. '15-no change 							
982	GUARD	RAIL	2	08-25-2015 08-26-2014	1 EA 1 EA	0	1	0 0	N/A N/A
	Notes:	982. Guardrail in place @ S co change. '14-spacer block miss		orthy end treatme	ents. Rail not attache		I posts in SV		
984	DRAINA	AGE	2	08-25-2015 08-26-2014	1 EA 1 EA	0 0	1 1	0 0	N/A N/A
	Notes:								
985	SLOPE	S	2	08-25-2015 08-26-2014	1 EA 1 EA	0	0 0	1 1	N/A N/A
	Notes:	985. S slope settled 3"-5" @ a paving(W.R. Meadows Seal Ti loose @ both abuts. Horiz crac seal has been installed along N	ght). Small spal ks in N. '13-S s	I @ bottom of S	slope paving. Erosio	n @ NW co	rner. '11-20'	of joint seal	
986	CURB 8	& SIDEWALK	2	08-25-2015 08-26-2014	1 EA 1 EA	0	0	1	N/A N/A
	Notes:	986. Trans, long and map crac change. '14-same. '15-cracks i	-	pproach curbs se		bar exp. Fe			
988	MISCEL	LANEOUS	2	08-25-2015 08-26-2014	1 EA 1 EA	1 1	0	0 0	N/A N/A
	Notes:	988. Lights attached to 2 sout on E rail.	nerly columns. I			-	-		
Genera	al Notes:	tes: *Bridge 27008 NB CSAH 81 (Broadway Ave)/Victory Mem Dr and Lowry Ave. 8/25/15. WJM and JDE.							
Ochere									
Concre		Recommended Repairs:							

300. Monitor strip seals. Seals are virtually closed.

301. Replace any missing or deteriorated poured joint material.

302. Reseal deck joints @ abut w/ hot pour.

311. Replace broken lateral restraint @ NW abut bearing.

331. Repair spall in SE approach railing.

379. Monitor deteriorated hinges. Repair box girder spalls and deterioration @ hinges.

407. Replace hot pour material @ S approach panel & seal long bit cracks in approach.

981. Replace horiz clearance marker(X4-4) in SW corner.

986. Repair curbs in SE & SW.

QTY

CS 5

0

0

N/A

Page 1 of 7

MINNESOTA STRUCTURE INVENTORY REPORT

Bridge ID: 27007

CSAH 81(SB) over MSAS 295; STR 184

Date: 06/10/2016

+ GENERAL +	+ ROADWAY +	+ INSPECTION +		
Agency Br. No.	Bridge Match ID (TIS) 1	Deficient Status S.D.		
District METRO Maint. Area	Roadway O/U Key 1-ON	Sufficiency Rating 24.9		
County 27 - HENNEPIN	Route Sys/Nbr CSAH 81	Last Inspection Date 08-25-2015		
City ROBBINSDALE	Roadway Name or Description	Inspection Frequency 12		
Township	CSAH 81 (BROADWAY) SB	Inspector Name HENNEPIN COUNTY		
Desc. Loc. 2.3 MI NW OF JCT TH 94	Roadwav Function MAINLINE	Status P-LOAD POSTED		
Sect., Twp., Range 08 - 029N - 24W	Roadway Type 1 WAY TRAF	+ NBI CONDITION RATINGS 4		
Latitude 45d 00m 48.38s	Control Section (TH Only)	Deck 5 % UNSOUND 5		
Longitude 93d 19m 07.99s	Ref. Point	Superstructure 4		
Custodian COUNTY	Date Opened to Traffic 01-01-1964	Substructure 6		
Owner COUNTY	Detour Length 1 mi.	Channel N		
Inspection By HENNEPIN COUNTY	Lanes 2 Lanes ON Bridge	Culvert N		
Year Built 1964	ADT (YEAR) 6,250 (2005)	+ NBI APPRAISAL RATINGS		
MN Year Remodeled	HCADT	Structure Evaluation 2		
FHWA Year Reconstructed	Functional Class. URB/MINOR ART	Deck Geometry 4		
Bridge Plan Location COUNTY	+ RDWY DIMENSIONS +	Underclearances 6		
Potential ABC N.A.	If Divided NB-EB SB-WB	Waterway Adequacy N		
	Roadway Width 30.0 ft	Approach Alignment 8		
+ STRUCTURE +	Vertical Clearance	+ SAFETY FEATURES +		
Service On HIGHWAY	Max. Vert. Clear.	Bridge Railing 1-MEETS STANDARDS		
Service Under HIGHWAY	Horizontal Clear. 29.9 ft	GR Transition 1-MEETS STANDARDS		
Main Span Type CCONC BOX GIRD	Lateral Cir Lt/Rt	Appr. Guardrail 1-MEETS STANDARDS		
Main Span Detail	Appr. Surface Width 30.0 ft	GR Termini 1-MEETS STANDARDS		
Appr. Span Type	Bridge Roadway Width 30.0 ft	+ IN DEPTH INSP. +		
Appr. Span Detail	Median Width on Bridge	Frac. Critical		
Skew	+ MISC. BRIDGE DATA +	Underwater		
Culvert Type	Structure Flared NO	Pinned Asbly.		
Barrel Length	Parallel Structure LEFT	Spec. Feat.		
Number of Spans	Field Conn. ID	+ WATERWAY +		
MAIN: 5 APPR: 0 TOTAL: 5	Cantilever ID	Drainage Area		
Main Span Length 102.5 ft	Foundations	Waterway Opening		
Structure Length 374.2 ft	Abut. CONC - FTG PILE	Navigation Control NOT APPL		
Deck Width 35.5 ft	Pier CONC - FTG PILE	Pier Protection		
Deck Material C-I-P CONCRETE	Historic Status NOT ELIGIBLE	Nav. Vert./Horz. Cir.		
Wear Surf Type LOW SLUMP CONC	On - Off System ON	Nav. Vert. Lift Bridge Clear.		
Wear Surf Install Year 1978	+ PAINT +	MN Scour Code A-NON WATERWAY		
Wear Course/Fill Depth 0.17 ft	Year Painted Pct. Unsound	Scour Evaluation Year 1991		
Deck Membrane NONE	Painted Area	+ CAPACITY RATINGS +		
	Primer Type			
Deck Rebars Install Year	Finish Type			
Structure Area 13,284 sq ft	+ BRIDGE SIGNS +	Inventory Rating HS 8.80		
Roadway Area 11,227 sq ft	Posted Load VEHICLE & SEMI	Posting VEH: 24 SEMI: 32 DBL: 32		
Sidewalk Width - L/R 1.1 ft 1.1 ft	Traffic NOT REQUIRED	Rating Date 01-09-2014		
Curb Height - L/R 0.67 ft 0.67 ft	Horizontal OBJECT MARKERS	Overweight Permit Codes		
Rail Codes - L/R 29 29	Vertical NOT APPLICABLE	A: N B: N C: N BRIDGE INVENTORY SUB REPORT		

BRIDGE INVENTORY SUB REPORT.RPT

6/10/2	2010								
		N	IINNESOTA BI	RIDGE II	NSPECTION	REPORT			
	-	NNEPIN COUNTY							
	GE 2700		OVER MSAS 295; S				P. DATE: 08-	25-2015	
City: Towns Sectio Span	n: 08 Tow Type: C0	SDALE nship: 029N Range: 24W CONC BOX GIRD	Route: CSAH 8 Control Section: Local Agency Brid	N	T TH 94 ⊳t.: 002+00.310 ∕laint. Area:	Length: 374 Deck Width: Rdwy. Area / Paint Area / F Culvert : N/	35.5 ft Pct. Unsnd: Pct. Unsnd:	11,227 se	q ft 5 %
Appra	isal Rating	Super: 4 Sub: 6 Chan: N s - Approach: 8 Waterway: Signs - Load Posting: VEHIC Horizontal: OBJECT	N M LE & SEMI Traffic:	Dpen, Posted IN Scour Co NOT REQU I: NOT APPL	de: A-NON WATI	D POSTED ERWAY De	Postings: 24 - f. Stat: S.D.	- 32 - 32 Suff. Rate	<u>e:</u> 24.9
ELE			INC			QTY	QTY	QTY	QTY
NE 800		ELEMENT NAME CAL DEFS OR SAFETY HAZ		P. DATE 5-2015	QUANTITY 1 EA	<u> </u>	<u>CS 2</u> 0	<u>CS 3</u> 0	<u>CS 4</u> 0
	Notes:	No critical structural deficier	icies or serious safety h	nazards are p	present on this struc	ure.			
16	REINF	ORCED CONCRETE TOP F	LANGE 08-2	5-2015	13,284 SF	13,018	0	266	(
	Notes:	359. Coping cracked and de & 25' on E side is spalled w/			nd rust on cantilever	s. '14-160' along	edge of deck or	n W side	
51	0 WEARI	NG SURFACE	08-2	5-2015	11,227 SF	10,104	0	1,123	(
		near both gutters. Conc sca (3"-4" deep) spalls @ joint			3 expansion joints. I	Diag crack in NE	and NW.'11-sev	/ere	
310	CONC	deteriorated/spalled. '15-de WEAR SURF-CRACKING S	eteriorated bit patch @				ut spall is		(
310	CONC Notes:	deteriorated/spalled. '15-de	eteriorated bit patch @ EALING 08-2 e are measurable in siz	<i>N abut has b</i> 5-2015 :e, most unse	oeen patched again. 0 LF ealed. '13-no change	Cracks were reco 0 '14-few large cr	ut spall is ently epoxy sea 0	led. 0	(
	Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some	eteriorated bit patch @ EALING 08-2 e are measurable in siz	<i>N abut has b</i> 5-2015 :e, most unse	oeen patched again. 0 LF ealed. '13-no change	Cracks were reco 0 '14-few large cr	ut spall is ently epoxy sea 0	led. 0	
	Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E doub	e are measurable in siz e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ i to joints. '13-85 deg - pint & 18' spalled @ N.	<u>N abut has b</u> 15-2015 26, most unse 5-all cracks r 15-2015 26 joints in '05 26 joint opene	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8	Cracks were reco 0 . '14-few large cr 1. 0 0 osed @ 70 deg(t "; N jt closed. '14	ut spall is ently epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @	led. 0 racks 0 1 1 side 2 all of S	
300	Notes: STRIP Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E doub SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle jo	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '14 08-2 sand. Conc repaired @ j to joints. '13-85 deg - oint & 18' spalled @ N. S jt-1/4".	<u>N abut has b</u> 15-2015 26, most unse 5-all cracks r 15-2015 26 joints in '05 26 joint opene	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8	Cracks were reco 0 . '14-few large cr 1. 0 0 osed @ 70 deg(t "; N jt closed. '14	ut spall is ently epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @	led. 0 racks 0 1 1 side 2 all of S	38
300	Notes: STRIP Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle je Deg. N jt-1/4"; Mid jt-3/8" &	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ j to joints. '13-85 deg - oint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat	<u>N abut has b</u> 15-2015 15-20	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat	Cracks were reco 0 . '14-few large or 1. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ut spall is ently epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ e open 3/8". '15- 5 . '14-joints from	led. 0 racks 0 1 side 2 all of S temp 60 0	38
300 301	Notes: STRIP Notes: POUR Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle jo Deg. N jt-1/4"; Mid jt-3/8" & E D SEAL JOINT 301. 4 joints in deck. Some	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ j to joints. '13-85 deg - oint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat ered; next has 1' not ac	<u>N abut has b</u> 15-2015 15-20	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat	Cracks were reco 0 . '14-few large or 1. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ut spall is ently epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ e open 3/8". '15- 5 . '14-joints from	led. 0 racks 0 1 side 2 all of S temp 60 0	38
300 301	Notes: STRIP Notes: POUR Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E doub SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle jo Deg. N jt-1/4"; Mid jt-3/8" & 3 ED SEAL JOINT 301. 4 joints in deck. Some S is OK; next has 2' not adh	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ j to joints. '13-85 deg - joint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat ered; next has 1' not ac 08-2 s. Hot pour over compr	<u>N abut has b</u> 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015	Deen patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat as 1' deck spall & 1' r 69 LF	Cracks were reco 0 . '14-few large or 1. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ut spall is antly epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ e open 3/8". '15- 5 . '14-joints from no change. 21	led. 0 racks 0 1 side 2 all of S temp 60 0 S to N; 0	38
300 301 302	Notes: STRIP Notes: POUR Notes: COMP Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls adj joint; 15' of spall @ middle jo Deg. N jt-1/4"; Mid jt-3/8" & ED SEAL JOINT 301. 4 joints in deck. Some S is OK; next has 2' not adh RESSION DECK JOINT 302. Joints @ N and S abut	e are measurable in siz be yellow is 1" wide. '14 08-2 sand. Conc repaired @ i to joints. '13-85 deg - bint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat ered; next has 1' not ac 08-2 s. Hot pour over compr ange.	<u>N abut has b</u> 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015 15-2015	Deen patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat as 1' deck spall & 1' r 69 LF	Cracks were reco 0 . '14-few large or 1. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ut spall is antly epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ e open 3/8". '15- 5 . '14-joints from no change. 21	led. 0 racks 0 1 side 2 all of S temp 60 0 S to N; 0	38
300 301 302	Notes: STRIP Notes: POUR Notes: COMP Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle je Deg. N jt-1/4"; Mid jt-3/8" & 3 ED SEAL JOINT 301. 4 joints in deck. Some S is OK; next has 2' not adh RESSION DECK JOINT 302. Joints @ N and S abut spalled @ N abut. '15-no ch	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ i to joints. '13-85 deg - joint & 18' spalled @ N. S jt-1/4". 08-2 ioint material deteriorat ered; next has 1' not ar 08-2 s. Hot pour over compr ange. LING 08-2 eathered. Conc spalled	N abut has b N abut has b 5-2015 e, most unsec- 5-all cracks r 5-2015 2 joints in '05 S joint opener Temp = 65 c $5-2015ed and/or mini-dhered; N has5-2015ession seals5-2015w/ rebar exp$	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat as 1' deck spall & 1' r 69 LF 5. '13-S joint looks go 748 LF b. Rust on conc. Crace	Cracks were reco 0 . '14-few large or 1. 0 osed @ 70 deg(t "; N jt closed. '14 sed. Mid & S are 139 erial deteriorated ot adhered. '15-r 30 od. N joint is dete	ut spall is antly epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ open 3/8". '15- 5 . '14-joints from to change. 21 eriorated. '14-5' 723	led. 0 racks 0 n 1 side 0 all of S temp 60 0 S to N; 0 is badly 25	38
300 301 302 3331	Notes: STRIP Notes: POUR Notes: COMP Notes: REINF Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls adj joint; 15' of spall @ middle ju Deg. N jt-1/4"; Mid jt-3/8" & 3 ED SEAL JOINT 301. 4 joints in deck. Some S is OK; next has 2' not adh RESSION DECK JOINT 302. Joints @ N and S abut spalled @ N abut. '15-no ch ORCED CONC BRIDGE RAI 331. Railing cracked and we	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ j to joints. '13-85 deg - joint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat ered; next has 1' not ac 08-2 s. Hot pour over compr ange. LING 08-2 eathered. Conc spalled ange. '14-same. '15-cra	N abut has b N abut has b 5-2015 e, most unsec- 5-all cracks r 5-2015 2 joints in '05 S joint opener Temp = 65 c $5-2015ed and/or mini-dhered; N has5-2015ession seals5-2015w/ rebar exp$	been patched again. 0 LF ealed. '13-no change recently epoxy seale 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat as 1' deck spall & 1' r 69 LF 5. '13-S joint looks go 748 LF b. Rust on conc. Crace	Cracks were reco 0 . '14-few large or 1. 0 osed @ 70 deg(t "; N jt closed. '14 sed. Mid & S are 139 erial deteriorated tot adhered. '15-r 30 od. N joint is dete	ut spall is antly epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ open 3/8". '15- 5 . '14-joints from to change. 21 eriorated. '14-5' 723	led. 0 racks 0 n 1 side 0 all of S temp 60 0 S to N; 0 is badly 25	(
810 300 301 302 3331 822	Notes: STRIP Notes: POUR Notes: COMP Notes: REINF Notes:	deteriorated/spalled. '15-de WEAR SURF-CRACKING S 358. Cracks are 5'-10', some are spalled. Crack in E dout SEAL DECK JOINT 300. Joints partially filled w/ to other). '12-conc spalls ad joint; 15' of spall @ middle je Deg. N jt-1/4"; Mid jt-3/8" & 3 ED SEAL JOINT 301. 4 joints in deck. Some S is OK; next has 2' not adh RESSION DECK JOINT 302. Joints @ N and S abut spalled @ N abut. '15-no ch ORCED CONC BRIDGE RAI 331. Railing cracked and we rust in NE corner. '13-no char	eteriorated bit patch @ EALING 08-2 e are measurable in siz ole yellow is 1" wide. '19 08-2 sand. Conc repaired @ j to joints. '13-85 deg - oint & 18' spalled @ N. S jt-1/4". 08-2 joint material deteriorat ered; next has 1' not ac 08-2 s. Hot pour over compr ange. LING 08-2 eathered. Conc spalled ange. '14-same. '15-cra VAY 08-2 settled w/ spalls in O/L.	N abut has b 25-2015 26, most unsection 25-2015 25-2015 20 joints in '05 25-2015 25-2015 25-2015 25-2015 25-2015 25-2015 25-2015 25-2015 25-2015 w/ rebar explacts have records 25-2015 '13-no chan	been patched again. 0 LF ealed. '13-no change recently epoxy sealed 115 LF 5. '11-joints almost cl ed +/- 3/8"; mid jt 1/8 deg. N joint is still clo 144 LF issing. '13-more mat as 1' deck spall & 1' r 69 LF 5. '13-S joint looks go 748 LF b. Rust on conc. Craw cently been sealed. 2 EA ge. '14-N is spalled of	Cracks were reco 0 . '14-few large cr 0 osed @ 70 deg(t "; N jt closed. '14 sed. Mid & S are 139 erial deteriorated ot adhered. '15-r 30 od. N joint is dete 0 cks epoxy sealed	ut spall is ently epoxy sea 0 racks & some cr 77 op of gland from -conc spalled @ open 3/8". '15- 5 . '14-joints from to change. 21 eriorated. '14-5' 723 in '05. Large sp 1	led. 0 racks 0 1 side 2 all of S temp 60 0 S to N; 0 is badly 25 palls & 0	38

deflection apparent minor. 2X 21 solid wirebar exp in bottom of grider @ hinge in span 4. Numerous pigeon appared § Singe. Spalled @ Singe. Spalls wirebar exp in both sides @ all hinges-no loss under bearings, and many other spails @ hinges. Many the tension cracks in both sides base in the spatial of the spalls @ hinge. Many the tension cracks in both. Haund above bearing in NL Win and SE is cracked. Wive all as spalls @ retear exp. Tension cracks in both minor base in Sull Fit hum and SE is cracked. Wive all as spalls @ retear exp. Tension cracks in pier columns. 205 REINFORCED CONCRETE COLUMN (0.4.2.5.2015 4.E.A 4 0 0 205 REINFORCED CONCRETE ABUTMENT (0.4.2.2015 4.E.A 4 0 0 215 REINFORCED CONCRETE ABUTMENT (0.4.2.2015 109 LF 20 88 1 Notes: 2016 (Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:20 CS2:20 CS3:0 CS4:0). 215. Utility opening bricks repaired @ S abut in 05. Hotic and vert cracks in both. Cracked and delam' conce. 216 Retreace and the delaminity opening bricks repaired @ S abut in 05. Hotic and vert cracks in both. Cracked and delamid conce. 216 Retreace and the delaminity. Singe Abutment 217. Legitt opening bricks repaired @ S abut in 05. Hotic and vert cracks in both. Cracked and delamid conce. 218.		Notes:	105. Large conc spall @ NE corner w/ ro cracks near columns. Water leakage un						Page 3 of 7
Just above bearing plate. WW has several mod or 205 REINFORCED CONCRETE COLUMN 08/25/2015 4 EA 4 0 0 206 REINFORCED CONCRETE COLUMN 08/25/2015 109 LF 20 88 1 215 REINFORCED CONCRETE ABUTIMENT 08/25/2015 109 LF 20 88 1 Notes: 2016/j Migrator added 40 LF to abutiment quantity to account for wingwalls (CS1:20 CS2/20 CS3/0 CS4/0). 215 CS3/0 CS4/0 20 88 1 Notes: 2016/j Migrator added 40 LF to abutiment quantity to account for wingwalls (CS1:20 CS2/20 CS3/0 CS4/0). 215 25 10 5 0 Virteffic in paraging pricks repaired @N & NE. 157 of minor to motify add britiz crask will ruistais in S1. 15 roo change. 10 5 0 211 EXPANSION BEARING 08/25/2015 25 EA 10 5 0 Notes: 311. Most exteritor bearings @ shout in Year exp above all of bearing area. Steel pad placad @NE bearing for support if failure excurs. Exterior bearing & an tozon. Ykoe ming & shout above and room the bearings. 8 1 2 Rotes: 317. Trans cracks in bottom. Conc deteriorated and spalled wireba			deflection apparent-minor. 2' X 2' spall v inside girder near hinge areas. Diag cra Spalled @ S hinge. Spalls w/ rebar exp hinges. Many fine tension cracks in bott	v/ rebar exp in bottom of g cks in conc above NW and on both sides @ all hinge om. Haunch above bearin	irder @ hinge in span d SE corner bearing. S s-no loss under bearin g in NE, NW and SE is	4. Numerous pi spalled @ E bea gs, and many o s cracked. NW i	igeon dropping aring pad @ S other spalls @ s also spalled	gs hinge. w/	
205 REINFORCED CONCRETE COLUMN 08-25-2015 4 EA 4 0 0 Notes: 205. Map cracks in pier columns: '13-'15-no change. 215 REINFORCED CONCRETE ABUTMENT 08-25-2015 109 LF 20 88 1 Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:20 CS2:20 CS3:0 CS4:0). 215. Utility opening bricks repaired @ S abut in '05. Honiz and ver tracks in both. Cracked and delaming from E is delaminating. "'14-effor in parapet @ NW & NE. 15' of minor to mod horiz cracks w' rust stains in S. 1 SF spall in SW comer. '15-no change. Wingwall notes: 397. A spall on roadway side of each S vall. '13-spalls have rebars exp. '14-SW & SE have minor spalls w' rebare exp. Minor hotiz crack in NW @ bottom. '15-no change. 0 311 EXPANSION BEARING 08-25-2015 25 EA 10 5 0 Notes: 311. Most exterior bearings & ship seals significantly rusted. Some bearings is gracked. Conc spalled above 2nd E bearing @ Subut shave pack rust and are frozen. Conc cracked and braken above and around NE bearing @ Natu spalled and eace @ NE bearing B shit. Ts' come spalled w' rebar exp above all 4 corine bearings. 851 CONCRETE HINGE ASSEMBLY 08-25-2015 3 EA 0 1 2 Notes: 37.7 Trans cracks in bottom. Conc deleriorated and spalled wi rebar exp. B & W fasacid span.3 Some iarge spalls @ span.3 are repaired. Numerous spal				-	n. Spall @ bearing in N	IE has gotten la	rger. Only con	c left is	
215 REINFORCED CONCRETE ABUTMENT 08-25-2015 109 LF 20 88 1 215 REINFORCED CONCRETE ABUTMENT 08-25-2015 109 LF 20 88 1 215 Utility opening bricks repaired (§ 3 abut in 05. Horiz and vert tracks in both. Cracked and delamit conc. Some rust staining. Major leakage in SE and in NE @ Utility blockout. '13-3 abut patch below 2nd beering from E1 is delaminating. '14-efftion in paragree (§ WA BALE. 15 of minor to mod horiz cracks / unst stains in S. 15 F spall in SW comer. '15-no change. 2111 EXPANSION BEARING 08-25-2015 25 EA 10 5 0 Notes: 311. Most exterior bearings (§ strip seels significantly rusted. Some bearing area. Steel op laced (§ NE bearing for support if failure occurs. Exterior bearings (§ 3 but and W bearing (§ N abut appear to have the start of the same problem. '13-all bearing (§ S abut and w rebar exp above all 4 comer bearing is: cracked. Conc spalled above 2nd E bearing (§ S abut and W bearing (§ N abut appear to have the start of the same problem. '13-all bearing (§ S abut and w rebar exp above all 4 comer bearing is: cracked. Some brage spalled (§ NE bearing (§ S abut and W bearing (§ N abut appear to have the start of the same problem. '15-no change. 861 CONCRETE HINGE ASSEMBLY 08-25-2015 3 EA 0 1 2 Notes: 379. Trans cracks in bottom. Conc deteriorated and spalled wi rebar exp (§ N hinge. 1.5 × 0 shang.'14-1 × 0' spall. Horc cappins (§ N hinge. 1.5 × 0' spall wi rebar e	205	REINF			4 EA	4	0	0	0
Notes: [2016] Migrator added 40 LF to abutment quantity to account for wingwalls (CS1:20 CS2:20 CS3:0 CS4:0). 215. Utility opening bricks repaired @ S abut in 05. Horiz and vert cracks in both. Cracked and delamit conc. Some rust staining, Major leakage in SE and in NE@ Utility blockout. '13-S abut patch below 2nd beering from E is delaminating. '14-effor in parsenge @ NW ARE. '15 of minor to mod horiz cracks with vert stains in 6. '15 spall in SW comer.'15-no change. '14-effor in parsenge @ NW ARE. '15 of minor to mod horiz cracks with vert stains in 6. '15 spalls have rebars exp. '14-SW & SE have minor spalls w/ rebar exp. Minor horiz crack in NW @ botom. '15-no change. '11 EXPANSION BEARING 08-25-2015 25 EA 10 5 0 Notes: 311. Most exterior bearings @ strip seals significantly rusted. Some bearing area. Steel pad placed @ NE bearing or support if failure occurs. Exteror bearings @ strip aeals significantly concer above NM bearing @ notex stain are forcen. 'Once cracked and broken above and around NE bearing.' alpha ba tappear to have the starf of the same problem. '13-all bearing @ stabut share pack rust & are frozen. 'Uncore above NM bearing is cracked. Conc spalled wirebar exp above all 4 corner bearings.' Botom span 2. Large spall. effor, cracking @ span 3 some large spalls @ span 3 are repaired. Numerous spalls @ wirebar exp in span 4. Large spalls @ wirebar exp in all spans.'14-rv & 's spall. effor, cracking, delams and reter showing @ span 2. Wire screen loose @ all hinges.'13-con deterorated & spalled wirebar exp in all spans.'14-rv & 's spall.'14' rust expear @ Nh hinge on E side.'15-no change.'' 861 CONCRETE HINGE ASSEMBLY <td< td=""><td></td><td>Notes:</td><td>205. Map cracks in pier columns. '13-'15</td><td>5-no change.</td><td></td><td></td><td></td><td></td><td></td></td<>		Notes:	205. Map cracks in pier columns. '13-'15	5-no change.					
215. Utility opening bricks repaired @ S abut in 05. Hortz and vert cracks in both. Cracket and delemid conc. Some rust statining. Migrie leakage in SE and in NE @ utility blockout. '13-s bat patch below 2nd bearing from E is deleminating. '14-effior in parapet @ NW & NE. 15' of minor to mod horiz cracks w' rust statins in S. 1 SF spall in SW corner. '15-no change. 311 EXPANSION BEARING 08-25-2015 25 EA 10 5 0 Notes: 311. Most exterior bearings @ stirp seals significantly rusted. Some bearings @ abuts have pack rust and are frozen. Conc cracked and broken above and around NE bearing. slight loss of bearing area. Steel pad placed @ NE bearing for support if failure occurs. Exterior bearings @ sturt and W bearing @ Nabut appear to have the start of the same problem. '13-all bearings @ stubt have pack rust and are frozen. Conc cracked and broken above and around NE bearing. @ Nabut appear to have the start of the same problem. '13-all bearings @ Stubt shave pack rust at a fer forcen.'14-doon: above NW bearing is oracked. Conc spalled above 2nd E bearing @ Sabut.'15-conc spalled w' rebar exp above all 4 corner bearings. 851 CONCRETE HINGE ASSEMBLY 08-25-2015 3EA 0 1 2 Notes: 379. Trans cracks in bottom. Conc deteriorated and spalled wi rebar exp @ Nabut erbar exp @ Nabue appear bitwe were appear @ Nabue appear and wire bare exp @ Nabue appear and area appear @ Nabue	215	REINF	ORCED CONCRETE ABUTMENT	08-25-2015	109 LF	20	88	1	0
rebar exp. Minor horiz crack in NW @ bottom. '16-no change. 311 EXPANSION BEARING 08-25-2015 25 EA 10 5 0 Notes: 311. Most extenior bearings @ strip seals significantly rusted. Some bearings @ abuts have pack rust and are frozen. Conc cracked and broken above and around NE bearing, slight loss of bearing area. Steel pad placed @ NE bearing for support if failure occurs. Exterior bearings @ S abut and W bearing @ N abut appear to have the start of the same problem. '13-all bearings @ abuts have pack rust & are frozen. '14-conc above NW bearing is cracked. Conc spalled with the same problem. '13-all bearings @ abuts have pack rust & are frozen. '14-conc above NW bearing is cracked. Conc spalled wither exp @ E & W fascia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spalls. Wirebar exp in all 3 spans. '14-1' x 6" spall wi rebar exp @ N hinge. 1.5' x 8" spall wi rebar exp @ N hinge on E side. '15-no change. 883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 0 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 892 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 0 0 0		Notes:	215. Utility opening bricks repaired @ S staining. Major leakage in SE and in NE '14-efflor in parapet @ NW & NE. 15' of	abut in '05. Horiz and ver @ utility blockout. '13-S a minor to mod horiz cracks	t cracks in both. Crack abut patch below 2nd b s w' rust stains in S. 1 \$	ed and delam'd bearing from E is SF spall in SW o	l conc. Some r s delaminating corner. '15-no	^{I.} change.	
Notes: 311. Most exterior bearings @ strip seals significantly rusted. Some bearings @ abuts have pack rust and are frozen. Conc cracked and broken above and around NE bearing, slight loss of bearing area. Steel pad placed @ NE bearing for support if failure occurs. Exterior bearings @ abuts have pack rust & are frozen. '14-conc above NW bearing is cracked. Conc spalled above 2nd E bearing @ sabut '14-conc shared w' thear exp above all 4 correr bearings. 851 CONCRETE HINGE ASSEMBLY 08-25-2015 3 EA 0 1 2 Notes: 379. Trans cracks in bottom. Conc deteriorated and spalled wi rebar exp ions pan 4. Large spalls wi rebar exp @ E & W facia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spall. efflor, cracking, delams and rebar showing @ span 2. Wire screen loose @ all hinges. '13-conc deteriorated & spalled wi rebar exp in all 3 spans. '14-'' X 8' spall wi rebar exp @ N hinge. 1.5' X 8' spall wi rebar exp @ N hinge. 1 0 883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 1 0 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 892 SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 893 SUPE Store VERTICAL CLR SIGNING 08-25-20				•	spails have repars exp	. 14-5VV & SE I	nave minor sp	ans w/	
cracked and broken above and around NE bearing, slight loss of bearing area. Steel pad placed @ NE bearing for support if failure occurs. Exterior bearings @ S abut and W bearing @ N abut appear to have the start of the same problem. '13-all bearings @ abuts have pack rust & are frozen. '14-conc above NW bearing is cracked. Conc spalled above 2nd E bearing @ 851 CONCRETE HINGE ASSEMBLY 08-25-2015 3 EA 0 1 2 Notes: 379. Trans cracks in bottom. Conc deteriorated and spalled w/ rebar exp in span 4. Large spalls w/ rebar exp @ E & W fascia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spall wiffor, cracking, delams and rebar showing @ span 2. Wire screen loose @ all hinges. '13-conc deteriorated & spalled wi rebar exp @ N hinge on E side. '15-no change. 883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 1 0 Notes: 965. '13-minor shear cracking of box girders present. '14-'16-no change. 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 Notes: 1961. Structure requires a vertical clearance sign or load posting sign. added @ bridge & SB approach. IS mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0	311	EXPA			25 EA	10	5	0	10
Notes: 379. Trans cracks in bottom. Conc deteriorated and spalled w/ rebar exp in span 4. Large spalls w/ rebar exp @ E & W fascia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spall, efflor, cracking, delams and rebar showing @ span 2. Wire screen loose @ all hinges. 13-conc deteriorated & spalled w/ rebar exp @ N hinge on E side. '15-no change. 883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 1 0 Notes: 965. '13-minor shear cracking of box girders present. '14-'15-no change. 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 Notes: [2016] Structure requires a vertical clearance sign or load posting sign. 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: [2016] Structure requires a vertical clearance sign or load posting sign. 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 892 SLOPES & Slope protection settled 3"-4". Slope paving has some cracks. '04-n		Notes:	cracked and broken above and around failure occurs. Exterior bearings @ S ab bearings @ abuts have pack rust & are	NE bearing, slight loss of l but and W bearing @ N ab frozen. '14-conc above N	bearing area. Steel par ut appear to have the N bearing is cracked.	d placed @ NE start of the sam	bearing for su le problem. '13	pport if 3-all	
fascia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spall, efflor, cracking, delams and rebar showing @ span 2. Wire screen loose @ all hinges. 1'3-conc deteriorated & spalled wirebar exp in all 3 spans. '14-1' x 6'' spall wirebar exp @ N hinge. 1.5' x 8'' spall wirebar exp @ N hinge on E side. '15-no change. 883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 1 0 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 893 GUARDRAIL 08-25-2015 1 EA 0 0 0 894 SLOPES & Slope protection settled 3''-4''. Slo	851	CONC	RETE HINGE ASSEMBLY	08-25-2015	3 EA	0	1	2	0
883 CONCRETE SHEAR CRACKING 08-25-2015 1 EA 0 1 0 Notes: 965. '13-minor shear cracking of box girders present. '14-'15-no change. 890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 Notes: [2016] Structure requires a vertical clearance sign or load posting sign. 1 0 0 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 <t< th=""><th></th><th>Notes:</th><th>fascia of span 3. Some large spalls @ s cracking, delams and rebar showing @</th><th>pan 3 are repaired. Nume span 2. Wire screen loose</th><th>rous spalls @ bottom @ all hinges. '13-con</th><th>span 2. Large s c deteriorated 8</th><th>pall, efflor, & spalled w/ re</th><th>bar</th><th></th></t<>		Notes:	fascia of span 3. Some large spalls @ s cracking, delams and rebar showing @	pan 3 are repaired. Nume span 2. Wire screen loose	rous spalls @ bottom @ all hinges. '13-con	span 2. Large s c deteriorated 8	pall, efflor, & spalled w/ re	bar	
890 LOAD PST OR VERTICAL CLR SIGNING 08-25-2015 1 EA 1 0 0 Notes: [2016] Structure requires a vertical clearance sign or load posting sign. 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 1 0 0 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc. - 1 EA 1 0 0	883	CONC							0
Notes: [2016] Structure requires a vertical clearance sign or load posting sign. 891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0		Notes:	965. '13-minor shear cracking of box gir	ders present. '14-'15-no c	hange.				
891 OTHER BRIDGE SIGNING 08-25-2015 1 EA 1 0 0 Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/. 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc. - 1 EA 1 0 0	890	LOAD	PST OR VERTICAL CLR SIGNING	08-25-2015	1 EA	1	0	0	0
Notes: 981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc. 1 0 0 0		Notes:	[2016] Structure requires a vertical clear	rance sign or load posting	sign.				
added @ bridge & SB approach in March. 892 SLOPES & SLOPE PROTECTION 08-25-2015 1 EA 0 0 0 Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc. 98-25-2015 1 EA 1 0 0	891	OTHE	R BRIDGE SIGNING	08-25-2015	1 EA	1	0	0	0
Notes: 985. S slope protection settled 3"-4". Slope paving has some cracks. '04-new joint seal @ abut slope paving(W.R. Meadows seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc.		Notes:	•		gn @ SW corner. '13-'	14-no change. '	15-load postin	ig signs	
seal tight). 15' loose @ both abuts. N slope settled +/- 1". '13-no change. '14-mod diag crack in N @ bottom W corner. (3-4) 3' trans cracks in N @ top on both sides. '15-new belting attached to N abut. 893 GUARDRAIL 08-25-2015 1 EA 1 0 0 Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 1 0 0 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc. - - - - -	892	SLOPI	ES & SLOPE PROTECTION	08-25-2015	1 EA	0	0	0	1
Notes: 982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change. 894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc.		Notes:	seal tight). 15' loose @ both abuts. N slo	ope settled +/- 1". '13-no c	hange. '14-mod diag c				
894 DECK & APPROACH DRAINAGE 08-25-2015 1 EA 1 0 0 Notes: 984. Drains have been plugged w/ conc.	893	GUAR	DRAIL	08-25-2015	1 EA	1	0	0	0
Notes: 984. Drains have been plugged w/ conc.		Notes:	982. Guardrail attached @ NW and NE	corners. '13-in good cond	ition. '14-same. '15-no	change.			
	894	DECK	& APPROACH DRAINAGE	08-25-2015	1 EA	1	0	0	0
895 SIDEWALK, CURB, & MEDIAN 08-25-2015 1 EA 0 1 0		Notes:	984. Drains have been plugged w/ conc						
	895	SIDEV	VALK, CURB, & MEDIAN	08-25-2015	1 EA	0	1	0	0

Page 3 of 7

								i uge + oi i					
	Notes:	•	cks in curbs. Repaired numerous are spalls in patched curb on E side. '13- epoxy sealed.										
899	MISC	ELLANEOUS ITEMS	08-25-2015	1 EA	1	0	0	0					
	Notes:	988. Bit pavement under is uneven. Roadway and curb settlement on Lowry +/- 75' W of SB Theo Wirth Pkwy. 3 lights mounted on center pier columns. Electrical conduit inside both fascias & outside W fascia. 2 new lights & conduit behind W rail. '13-new bit on Lowry W of Theo Wirth. Curb & gutter, CB & bit median improvements and repairs to Lowry EB & WB.											
900	PROT	ECTED SPECIES	08-25-2015	1 EA	1	0	0	0					
	Notes:	: Use this element to track the presence of protected species living on this structure.											
	General Notes:												
		Recommended Repairs:											
		22. Repair spalls @ strip seal	joints.										
		105. Remove numerous pigeor personnel.	droppings inside girders near hinge	areas. Health risk to i	nspection and o	operations							
		105. Monitor box girders near of											
		105. Repair conc @ hinge joint											
		105. Monitor deteriorated botto	m of girders. g @ NE corner. Clean/blast/repair be	arings @ abuts									
		359. Repair spalls @ deck edg		anngs @ abuts.									
		379. Repair box girder spalls an	nd deterioration @ hinges.										

Page 4 of 7

06/10/2016

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM

Inspected by: HENNEPIN COUNTY

ELEM						QTY	QTY	QTY	QTY	QT
NBR		ELEMENT NAME	ENV	INSP. DATE	QUANTITY	CS 1	CS 2	CS 3	CS 4	CS
22	LS O/L	(CONC DECK)	3	08-25-2015 08-26-2014	13,283 SF 13,283 SF	0 0	0 0	13,283 13,283	0 0	
	Notes:	22. Large trans and long crack each side of all 3 expansion join repaired w/ bit. '13-no change. has been patched again. Crack	nts. Diag crack 14-bit patch @	in NE and NW.'1 N abut spall is d	1-severe (3"-4" dee	ep) spalls @ j	joint @ N a	abut-'12-spall	s	
300	STRIP	SEAL JOINT	3	08-25-2015 08-26-2014	115 LF 115 LF	0 0	77 77	38 38	N/A N/A	N/# N/#
	Notes:	300. Joints partially filled w/ sa side to other). '12-conc spalls a all of S joint; 15' of spall @ mid '15-temp 60 Deg. N jt-1/4"; Mid	dj to joints. '13- dle joint & 18' s	85 deg - S joint o palled @ N. Terr	opened +/- 3/8"; mic	d jt 1/8"; N jt o	closed. '14	-conc spalled	@	
301	POURE	ED DECK JOINT	3	08-25-2015 08-26-2014	144 LF 144 LF	139 139	5 5	0 0	N/A N/A	N/A N/A
	Notes:	301. 4 joints in deck. Some join N; S is OK; next has 2' not adh		riorated and/or m	nissing. '13-more m	aterial deterio	orated. '14	-joints from S		
302	COMPF	RESSION JOINT	3	08-25-2015 08-26-2014	69 LF 69 LF	30 30	21 21	18 18	N/A N/A	N/A N/A
	Notes:	302. Joints @ N and S abuts. I badly spalled @ N abut. '15-no		ompression seal	s. '13-S joint looks g	good. N joint	is deterior	ated. '14-5' is		
407	BITUMI	NOUS APPROACH	2	08-25-2015 08-26-2014	2 EA 2 EA	1 0	1 2	0 0	0 0	N/A N/A
	Notes:	407. Long cracks in S. S is set '15-spalls in N are repaired. Se				d @ deck. Lo	ong cracks	in S are large	9.	
331	CONCF	RETE RAILING	3	08-25-2015 08-26-2014	748 LF 748 LF	0 0	723 723	25 25	0 0	N/A N/A
	Notes:	331. Railing cracked and weat & rust in NE corner. '13-no cha	•		•		sealed in 'C)5. Large spa	lls	
105	CONCF	RETE BOX GIRDER	4	08-25-2015 08-26-2014	374 LF 374 LF	0 0	345 347	25 25	4 2	N/A N/A
	Notes:	[105. Large conc spall @ NE co Shear cracks near columns. We term deflection apparent-minor. droppings inside girder near hir pad @ S hinge. Spalled @ S hi other spalls @ hinges. Many fir also spalled w/ rebar exp. Tens Many spalls w/ rebar exp in W larger. Only conc left is just abo no immediate repairs or new lo box cracked & spalled @ N abo size. 4 SF spall w/ rebar exp @ spall @ drain tube near N hinger rebar exp in coping(above vert above NW & SE bearings; .5 S	ater leakage un , 2' X 2' spall w/ nge areas. Diag nge. Spalls w/ n the tension crack ion cracks in al cantilever. '13-s tove bearing plat ad rating require that above 2nd be hinge in span e on W side. 22 face of box). Sp	der E side @ col rebar exp in bot cracks in conc a rebar exp on bot s in bottom. Hau I fascias near ab crape on unders e. NW has sever ed. '14-mod long aring from E. Dia 4 is now 3' x 3'. 2 5 LF of vert crac ball w/ rebar exp	umns 2 and 3. Mar tom of girder @ hin bove NW and SE of n sides @ all hinger inch above bearing uts. Trans cracks of ide @ WB left turn. ral mod cracks just cracks w/ efflor & r ag cracks in conc al 2 SF & 1 SF spall w ks in W side & 175 in E side of box @	y vert cracks ge in span 4. corner bearing s-no loss und in NE, NW a n cantilever of Spall @ bea above bearin ust stains in bove NW & S / rebar exp in LF in E side S hinge. '15-	s on sides of Numerous g. Spalled ler bearing and SE is c of box girde tring in NE g. Enginee E coping (SE bearing the face of of box. 50	of girders. Lo s pigeon @ E bearing s, and many racked. NW i ers in all spar has gotten er's opinion th @ P3. Bottom s are mod in box @ P2. 2' SF of spall w	s is. at of x 6" /	

06/10/2016

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM

Inspected by: HENNEPIN COUNTY **BRIDGE 27007** CSAH 81(SB) OVER MSAS 295; STR 184 INSP. DATE: 08-25-2015 ELEM QTY QTY QTY QTY QTY NBR ELEMENT NAME ENV INSP. DATE QUANTITY CS 1 CS 2 CS 3 CS₄ CS 5 CONCRETE HINGE 08-25-2015 0 0 N/A 379 4 3 FA 1 2 08-26-2014 3 EA 0 2 0 N/A Notes: |379. Trans cracks in bottom. Conc deteriorated and spalled w/ rebar exp in span 4. Large spalls w/ rebar exp @ E & W fascia of span 3. Some large spalls @ span 3 are repaired. Numerous spalls @ bottom span 2. Large spall, efflor, cracking, delams and rebar showing @ span 2. Wire screen loose @ all hinges. '13-conc deteriorated & spalled w/ rebar exp in all 3 spans. '14-1' x 6" spall w/ rebar exp @ N hinge. 1.5' x 8" spall w/ rebar exp @ N hinge on E side. '15-no change. **EXPANSION BEARING** 4 08-25-2015 10 N/A 311 25 FA 10 5 N/A 08-26-2014 25 EA 5 10 N/A 10 N/A Notes: |311. Most exterior bearings @ strip seals significantly rusted. Some bearings @ abuts have pack rust and are frozen. Conc cracked and broken above and around NE bearing, slight loss of bearing area. Steel pad placed @ NE bearing for support if failure occurs. Exterior bearings @ S abut and W bearing @ N abut appear to have the start of the same problem. '13-all bearings @ abuts have pack rust & are frozen. '14-conc above NW bearing is cracked. Conc spalled above 2nd E bearing @ S abut. '15-conc spalled w/ rebar exp above all 4 corner bearings.| 205 CONCRETE COLUMN 4 08-25-2015 4 EA 4 0 0 0 N/A 4 EA 08-26-2014 4 0 0 0 N/A Notes: |205. Map cracks in pier columns. '13-'15-no change.| 215 CONCRETE ABUTMENT 08-25-2015 69 LF 0 68 0 4 1 N/A 08-26-2014 69 LF 0 68 1 0 N/A Notes: |215. Utility opening bricks repaired @ S abut in '05. Horiz and vert cracks in both. Cracked and delam'd conc. Some rust staining. Major leakage in SE and in NE @ utility blockout. '13-S abut patch below 2nd bearing from E is delaminating. '14-efflor in parapet @ NW & NE. 15' of minor to mod horiz cracks w' rust stains in S. 1 SF spall in SW corner. '15-no change. CONCRETE WINGWALL 08-25-2015 4 EA 2 2 0 0 387 4 N/A 08-26-2014 4 EA 2 2 0 0 N/A Notes: [387. A spall on roadway side of each S wall. '13-spalls have rebars exp. '14-SW & SE have minor spalls w/ rebar exp. Minor horiz crack in NW @ bottom. '15-no change.| CONC DECK CRACKING 08-25-2015 N/A 358 2 1 EA 0 0 0 1 08-26-2014 1 EA 0 0 0 N/A 1 Notes: |358. Cracks are 5'-10', some are measurable in size, most unsealed. '13-no change. '14-few large cracks & some cracks are spalled. Crack in E double yellow is 1" wide. '15-all cracks recently epoxy sealed.] CONC DECK UNDERSIDE 0 0 359 3 08-25-2015 1 F 4 Ω 1 0 08-26-2014 1 EA 0 0 0 0 Notes: [359. Coping cracked and delam'd w/ rebar exp. Delam, efflor and rust on cantilevers. '14-160' along edge of deck on W side & 25' on E side is spalled w/ rebar exp. '15-no change.| CRITICAL FINDING 08-25-2015 1 EA 0 N/A N/A N/A 964 2 1 08-26-2014 1 EA 0 N/A N/A N/A 1 |964.| Notes: SHEAR CRACKING 08-25-2015 0 N/A 965 2 1 EA 0 0 1 08-26-2014 1 EA 0 1 0 0 N/A [965. '13-minor shear cracking of box girders present. '14-'15-no change.] Notes: 981 SIGNING 2 08-25-2015 1 FA 1 0 0 0 0 08-26-2014 1 EA 1 0 0 0 0 Notes: 1981. Horiz clearance markers X4-4 @ N approach. 15 mph exit sign @ SW corner. '13-'14-no change. '15-load posting signs added @ bridge & SB approach in March.| 982 **GUARDRAIL** 2 08-25-2015 1 EA 0 0 N/A N/A 1 08-26-2014 1 EA 0 0 N/A N/A 1 Notes: [982. Guardrail attached @ NW and NE corners. '13-in good condition. '14-same. '15-no change.]

06/10/2016

MINNESOTA BRIDGE INSPECTION REPORT OLD ELEMENT SYSTEM


Inspected by: HENNEPIN COUNTY

BRIDG	E 27007	7 CSAH 81(SB) OVE	R MSAS 298	5; STR 184			INSP. DA	TE: 08-25	-2015				
ELEM NBR		ELEMENT NAME	ENV	INSP. DATE	QUANTITY	QTY CS 1	QTY CS 2	QTY CS 3	QTY CS 4	QT CS			
984	DRAINA		2	08-25-2015 08-26-2014	1 EA 1 EA	1 1	0 0	0 0	N/A N/A	N// N//			
	Notes:	984. Drains have been plugged	l w/ conc.										
985	SLOPES	3	2	08-25-2015 08-26-2014	1 EA 1 EA	0 0	0 0	1 1	N/A N/A	N/A N/A			
	Notes:	985. S slope protection settled Meadows seal tight). 15' loose of corner. (3-4) 3' trans cracks in N	@ both abuts. N	I slope settled +/	'- 1". '13-no change.	. '14-mod dia		0.	W				
986	CURB &	SIDEWALK	2	08-25-2015 08-26-2014	1 EA 1 EA	0 0	1 1	0 0	N/A N/A	N/A N/A			
	Notes:	986. Some trans and long cracks in curbs. Repaired numerous areas of severely spalled curb on E rail in '05. Small spall @ SW & NE approach. Small spalls in patched curb on E side. '13-no change. '14-cracks are mod in size & rust stained. '15-cracks have recently been epoxy sealed.											
988	MISCEL	LANEOUS	2	08-25-2015 08-26-2014	1 EA 1 EA	1 1	0 0	0 0	N/A N/A	N/# N/#			
	Notes:	988. Bit pavement under is une mounted on center pier column W rail. '13-new bit on Lowry W (WB.	s. Electrical con	duit inside both	fascias & outside W	fascia. 2 ne	w lights & c	onduit behir	nd				
Genera	I Notes:	*Bridge 27007 SB CSAH 81 (Broadway Ave)/	EB Lowry, Victo	ry Mem Pkwy 8/25/	15 WJM and	I JDE.						
		Recommended Repairs:											
		 Repair spalls @ strip sea Remove numerous piged personnel. Monitor box girders near Repair conc @ hinge joir Monitor deteriorated bott Monitor blocked up beari 	over bearings ins over bearings (nts and copings om of girders.	@ abuts. of boxes.	-		ection and o	operations					
		359. Repair spalls @ deck ed 379. Repair box girder spalls	ges & cantileve	rs.	pan bearings @ abo								

CSAH 081 (Bottineau Boulevard) - Northbound Bridge

Existing Typical Cross Section


Total Width: 35.5 ft



CSAH 081 (Bottineau Boulevard) - Southbound Bridge

Existing Typical Cross Section


Total Width: 35.5 ft



CSAH 081 (Bottineau Boulevard) - Northbound Bridge

Proposed Typical Cross Section


Total Width: 48.34 ft



CSAH 081 (Bottineau Boulevard) - Southbound Bridge

Proposed Typical Cross Section

Total Width: 48.34 ft















Classification Grand Totals

CLASS COUNT DATA CSAH 81 N. OF LOWRY AVE. BRIDGE

Site: 01 Monday, 10/20/2014 9:00 AM -Wednesday, 10/22/2014 9:00 AM

Hourly Averages															
						п	NB.	ages							
Interval Start	Total	Motor Bikes	Cars & Trailers	2 Axle Long	Buses	2 Axle 6 Tire	3 Axle Single	4 Axle Single	<5 Axle Double	5 Axle Double	>6 Axle Double	<6 Axle Multi	6 Axle Multi	>6 Axle Multi	Tailgating
12:00 AM	51.0	0.5	40.5	8.0	0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1:00 AM	30.0	0.0	24.5	4.5	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
2:00 AM	22.0	0.0	17.5	3.5	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
3:00 AM	22.0	0.0	15.0	3.5	0.0	3.0	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
4:00 AM	71.5	0.5	57.5	8.0	1.5	3.0	0.0	0.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0
5:00 AM	140.5	0.5	109.0	18.0	5.0	6.5	0.0	0.0	1.5	0.0	0.0	0.0	0.0	0.0	0.0
6:00 AM	276.5	1.0	194.5	44.5	9.0	23.5	1.0	0.0	2.5	0.0	0.0	0.5	0.0	0.0	0.0
7:00 AM	389.0	3.0	270.5	59.5	14.5	31.5	2.0	0.0	5.5	1.0	0.5	0.5	0.0	0.5	0.0
8:00 AM	370.0	3.5	264.0	66.0	11.0	23.0	1.0	0.0	1.5	0.0	0.0	0.0	0.0	0.0	0.0
9:00 AM	321.0	1.5	220.5	68.5	6.5	20.5	1.0	0.0	1.5	1.0	0.0	0.0	0.0	0.0	0.0
10:00 AM	328.5	3.0	232.5	65.5	4.0	19.5	0.0	0.0	3.5	0.0	0.0	0.5	0.0	0.0	0.0
11:00 AM	344.0	3.0	251.0	61.0	5.0	16.5	1.5	1.0	3.5	1.0	0.0	0.5	0.0	0.0	0.0
12:00 PM	396.0	3.5	282.0	72.0	13.5	19.0	3.0	0.0	3.0	0.0	0.0	0.0	0.0	0.0	0.0
1:00 PM	411.5	4.0	298.5	73.5	12.0	18.0	1.5	0.0	2.5	1.0	0.0	0.5	0.0	0.0	0.0
2:00 PM	479.5	9.0	334.0	96.0	11.0	22.0	0.0	0.0	4.5	1.5	0.5	1.0	0.0	0.0	0.0
3:00 PM	588.0	5.5	438.5	93.0	15.0	27.5	2.5	0.0	6.0	0.0	0.0	0.0	0.0	0.0	0.0
4:00 PM	753.0	9.5	587.0	102.0	18.0	22.5	1.0	0.0	11.5	1.0	0.0	0.5	0.0	0.0	0.0
5:00 PM	807.5	9.0	626.0	96.5	22.5	36.5	3.0	0.0	12.0	0.5	0.0	1.0	0.0	0.5	0.0
6:00 PM	543.5	5.0	428.5	69.5	12.5	22.0	0.0	0.0	5.5	0.0	0.0	0.5	0.0	0.0	0.0
7:00 PM	354.5	4.0	277.0	54.0	1.5	14.5	0.5	0.0	2.5	0.0	0.0	0.5	0.0	0.0	0.0
8:00 PM	272.5	2.0	215.5	39.0	2.0	11.0	0.5	0.0	2.0	0.0	0.0	0.5	0.0	0.0	0.0
9:00 PM	204.5	2.5	165.5	27.0	1.0	7.5	0.5	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
10:00 PM	167.0	0.5	136.0	21.0	0.5	7.5	0.0	0.0	1.0	0.0	0.5	0.0	0.0	0.0	0.0
11:00 PM	77.0	0.0	65.0	9.5	0.0	1.5	0.5	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
Daily Average	7420.5	71.0	5550.5	1163.5	166.0	360.5	19.5	1.0	72.5	7.0	1.5	6.5	0.0	1.0	0.0
						Stu	idy Grand 1	Totals							
	Total	Motor Bikes	Cars & Trailers	2 Axle Long	Buses	2 Axle 6 Tire	3 Axle Single	4 Axle Single	<5 Axle Double	5 Axle Double	>6 Axle Double	<6 Axle Multi	6 Axle Multi	>6 Axle Multi	Tailgating
NB.	14841	142	11101	2327	332	721	39	2	145	14	3	13	0	2	0
		1.0 %	74.8 %	15.7 %	2.2 %	4.9 %	0.3 %	0.0 %	1.0 %	0.1 %	0.0 %	0.1 %	0.0 %	0.0 %	0.0 %
		NOR	THBOUN	ND - SUN	۸ OF Tł	HE DAIL	Y AVER	AGE OF		ES 4 TH	ROUG	+ 13 =	638		
						HE DAIL							475		
						OMMERC								,113	

1

Classification Grand Totals

CLASS COUNT DATA CSAH 81 N. OF LOWRY AVE. BRIDGE

Site: 01 Monday, 10/20/2014 9:00 AM -Wednesday, 10/22/2014 9:00 AM

	Hourly Averages SB.														
Interval Start	Total	Motor Bikes	Cars & Trailers	2 Axle Long	Buses	2 Axle 6 Tire	3 Axle Single	4 Axle Single	<5 Axle Double	5 Axle Double	>6 Axle Double	<6 Axle Multi	6 Axle Multi	>6 Axle Multi	Tailgating
12:00 AM	57.5	0.5	47.5	9.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1:00 AM	45.5	0.5	32.0	12.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
2:00 AM	27.5	0.0	24.0	3.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
3:00 AM	21.5	0.0	17.0	4.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
4:00 AM	37.0	0.0	25.5	9.5	0.5	0.0	0.0	0.0	1.5	0.0	0.0	0.0	0.0	0.0	0.0
5:00 AM	113.0	0.5	81.5	27.5	0.5	2.0	1.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
6:00 AM	282.0	2.0	198.5	56.5	10.5	8.0	0.5	0.0	5.0	0.5	0.0	0.0	0.0	0.5	0.0
7:00 AM	622.5	1.5	460.0	105.5	21.0	13.5	1.0	0.0	13.0	1.5	0.0	5.0	0.0	0.0	0.5
8:00 AM	566.5	3.0	399.5	94.0	30.0	23.0	2.5	0.0	9.5	2.5	0.0	1.5	0.0	1.0	0.0
9:00 AM	370.0	1.0	255.5	82.5	9.0	12.0	2.0	0.5	6.0	0.5	0.0	0.5	0.5	0.0	0.0
10:00 AM	347.0	2.0	244.5	80.0	8.0	6.5	1.5	0.0	3.0	0.5	0.0	0.5	0.0	0.0	0.5
11:00 AM	370.0	1.0	268.5	77.5	5.0	10.0	3.5	0.5	1.5	1.5	0.0	1.0	0.0	0.0	0.0
12:00 PM	398.0	3.5	288.5	74.5	7.5	15.5	2.0	0.5	3.5	0.5	0.0	2.0	0.0	0.0	0.0
1:00 PM	414.0	1.0	304.0	81.0	8.5	10.5	1.5	0.0	5.5	0.5	0.0	1.5	0.0	0.0	0.0
2:00 PM	456.0	1.5	328.0	94.5	14.0	10.5	0.5	0.5	6.0	0.0	0.0	0.5	0.0	0.0	0.0
3:00 PM	540.0	2.0	411.5	93.5	8.5	11.5	3.0	0.0	8.0	1.0	0.0	1.0	0.0	0.0	0.0
4:00 PM	601.0	1.5	451.0	106.0	22.0	11.5	0.0	0.5	7.0	0.5	0.0	0.5	0.0	0.0	0.5
5:00 PM	590.0	2.5	463.0	95.0	13.0	6.5	0.0	0.0	8.0	0.0	0.0	2.0	0.0	0.0	0.0
6:00 PM	452.0	1.5	352.5	79.5	10.0	4.5	0.0	0.0	2.5	0.0	0.0	1.0	0.0	0.0	0.5
7:00 PM	367.5	1.0	292.0	64.5	4.0	3.5	0.5	0.0	2.0	0.0	0.0	0.0	0.0	0.0	0.0
8:00 PM	294.0	0.5	239.5	44.5	1.5	4.5	0.0	0.0	2.5	0.0	0.0	0.5	0.0	0.5	0.0
9:00 PM	215.5	0.0	178.5	33.0	1.0	2.0	0.5	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
10:00 PM	157.5	0.5	131.0	23.5	0.0	2.0	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
11:00 PM	98.5	1.0	82.5	13.5	0.5	0.5	0.0	0.0	0.5	0.0	0.0	0.0	0.0	0.0	0.0
Daily Average	7444.0	28.5	5576.0	1364.5	176.0	159.0	20.0	2.5	86.0	9.5	0.0	17.5	0.5	2.0	2.0
						Stu	udy Grand 1	otals							_
	Total	Motor Bikes	Cars & Trailers	2 Axle Long	Buses	2 Axle 6 Tire	3 Axle Single	4 Axle Single	<5 Axle Double	5 Axle Double	>6 Axle Double	<6 Axle Multi	6 Axle Multi	>6 Axle Multi	Tailgating
SB.	14888	57	11152	2729	352	318	40	5	172	19	0	35	1	4	4
		0.4 %	74.9 %	18.3 %	2.4 %	2.1 %	0.3 %	0.0 %	1.2 %	0.1 %	0.0 %	0.2 %	0.0 %	0.0 %	0.0 %

1

TOTAL VOLUME DATA CSAH # 81 @ LOWRY AVE. BRIDGE/ NB, # 81 / STUDY # 4062 Site: 01

NB, # 81 / STUDY # 4062										
	Weekly Volume, per Channel									
				N.E	3.					
Interval Start	Mon 5/16/2016	Tue 5/17/2016	Wed 5/18/2016	Thu 5/19/2016	Fri 5/20/2016	Sat 5/21/2016	Sun 5/22/2016	Mon - Fri Average	Weekly Average	
12:00 AM	-	44	58	-	-	-	-	51.0	51.0	
1:00 AM	-	24	30	-	-	-	-	27.0	27.0	
2:00 AM	-	20	17	-	-	-	-	18.5	18.5	
3:00 AM	-	18	16	-	-	-	-	17.0	17.0	
4:00 AM	-	29	25	-	-	-	-	27.0	27.0	
5:00 AM	-	80	70	-	-	-	-	75.0	75.0	
6:00 AM	-	128	120	-	-	-	-	124.0	124.0	
7:00 AM	-	222	225	-	-	-	-	223.5	223.5	
8:00 AM	-	216	215	-	-	-	-	215.5	215.5	
9:00 AM	-	178	205	-	-	-	-	191.5	191.5	
10:00 AM	-	222	216	-	-	-	-	219.0	219.0	
11:00 AM	232	244	-	-	-	-	-	238.0	238.0	
12:00 PM	256	284	-	-	-	-	-	270.0	270.0	
1:00 PM	307	260	-	-	-	-	-	283.5	283.5	
2:00 PM	300	344	-	-	-	-	-	322.0	322.0	
3:00 PM	408	370	-	-	-	-	-	389.0	389.0	
4:00 PM	508	576	-	-	-	-	-	542.0	542.0	
5:00 PM	544	586	-	-	-	-	-	565.0	565.0	
6:00 PM	335	351	-	-	-	-	-	343.0	343.0	
7:00 PM	255	258	-	-	-	-	-	256.5	256.5	
8:00 PM	210	219	-	-	-	-	-	214.5	214.5	
9:00 PM	166	174	-	-	-	-	-	170.0	170.0	
10:00 PM	108	145	-	-	-	-	-	126.5	126.5	
11:00 PM	78	70	-	-	-	-	-	74.0	74.0	
Totals	3707	5062	1197	0	0	0	0	4983.0	4983.0	
				<u>Peak</u> H	lours					
12:00 AM - 12:00 PM	11:00 AM	11:00 AM	7:00 AM	-	-	-	-	11:00 AM	11:00 AM	
Volume	232	244	225	-	-	-	-	238.0	238.0	
12:00 PM - 12:00 AM	5:00 PM	5:00 PM	-	-	-	-	-	5:00 PM	5:00 PM	
Volume	544	586	-	-	-	-	-	565.0	565.0	

RAW TOTAL:	13,540
ADJUSTMENT FACTOR:	1.122

2016 AADT: 12,100

TOTAL VOLUME DATA CSAH # 81 @ LOWRY AVE. BRIDGE / SB. # 81 / STUDY # 4063

344

879

714

384

358

388

725

_

-

-

-

_

_

374

659

360

818

682

414

356

Site: 01

Weekly

Average

59.0

29.5

23.0

33.0

119.5

352.0

848.5

698.0

399.0

357.0

381.0

Mon - Fri

Average

59.0

29.5

23.0

33.0

119.5

352.0

848.5

698.0

399.0

357.0

381.0

-

_

_

_

_

-

-

-

_

_

_

_

_

682.5

682.5

	Weekly Volume, per Channel											
		S.B.										
Interval Start	Mon 5/16/2016	Tue 5/17/2016	Wed 5/18/2016	Thu 5/19/2016	Fri 5/20/2016	Sat 5/21/2016	Sun 5/22/2016					
12:00 AM	-	62	56	-	-	-	-					
1:00 AM	-	27	32	-	-	-	-					
2:00 AM	-	20	26	-	-	-	-					
3:00 AM	-	30	36	-	-	-	-					
4:00 AM	-	114	125	-	-	-	-					

-

-

-

-

_

-

-

_

-

-

_

_

_

_ 429.0 440 11:00 AM 418 _ _ _ _ 429.0 447.5 12:00 PM 442 453 _ _ _ _ _ 447.5 1:00 PM 504 461 -----482.5 482.5 2:00 PM 598 578 _ _ _ _ _ 588.0 588.0 3:00 PM 659 648 -----653.5 653.5 640 4:00 PM 725 -682.5 682.5 _ 508 5:00 PM 521 _ _ _ _ _ 514.5 514.5 376 6:00 PM 384 380.0 380.0 _ ----7:00 PM 357.5 365 350 357.5 _ -_ --295.0 274 316 295.0 8:00 PM ---_ -9:00 PM 210 242 226.0 226.0 --_ --10:00 PM 133.0 133 133 -----133.0 11:00 PM 64 72 --_ --68.0 68.0 Totals 0 5565 8643 2905 0 0 0 8556.5 8556.5 Peak Hours 12:00 AM -11:00 AM 6:00 AM 6:00 AM _ -6:00 AM 6:00 AM _ 12:00 PM 879 818 _ 848.5 848.5 418 _ -Volume 12:00 PM -3:00 PM 4:00 PM 4:00 PM 4:00 PM _ _ _ _ _ 12:00 AM

_

4:00 AM

5:00 AM

6:00 AM

7:00 AM

8:00 AM

9:00 AM

Volume

10:00 AM

From:	<u>Filipi, Mark</u>
То:	Sierra Saunders
Cc:	Jason R Pieper; Jason D Gottfried; Carla J Stueve; Robert H. Byers
Subject:	RE: 2016 Regional Solicitation - Forecast AADT"s
Date:	Thursday, June 16, 2016 10:23:49 AM
Attachments:	image006.png image008.png image010.png

Sierra,

Here is the data you requested. It is generated from the model runs from the most recent update of the Council's 2040 Transportation Policy Plan and is based in the four-step trip-based regional travel demand forecast model.

Project	Forecast Volume
CSAH 15 (Shoreline Dr) Bridge Replacement	20,900
CSAH 19 (Manitou Rd/Shadywood Rd) Bridge Rehabilita	tion 16,200
CSAH 23 (Marshall St NE)	10,500
CSAH 32 (Penn Ave) Reconstruction	16,200 (Note: The 2014 AADT
you cite of 12,800 is actually outside	
	your project area. 10,800 is
	the only AADT reported in your
	project area)
CSAH 66 (Golden Valley Rd) Reconstruction	19,900 (West of Noble Ave.)
	10,200 (East of Indiana Ave.)
CSAH 81 (Bottineau Blvd) Expansion	51,100
CSAH 81 (Broadway Ave) Bridge Replacement	24,700
CSAH 152 (Webber Pkwy) Reconstruction	This roadway is not in the regional model.
	The model links in the area show an
	annualized
	growth rate of 0.5%. When applied
	to the 13,700
	2013 volume, this grows to 16,100.

If you have any questions, please feel free to contact me.



Mark Filipi, AICP PTP Manager, Technical Planning Support Metropolitan Transportation Services mark.filipi@metc.state.mn.us P.651.602.1725 | F.651.602.1739 390 North Robert Street | St. Paul, MN | 55101 | metrocouncil.org From: Sierra Saunders [mailto:Sierra.Saunders@hennepin.us]
Sent: Wednesday, June 15, 2016 8:02 AM
To: Filipi, Mark <Mark.Filipi@metc.state.mn.us>
Cc: Jason R Pieper <Jason.Pieper@hennepin.us>; Jason Gottfried <Jason.gottfried@hennepin.us>; Carla Stueve <Carla.Stueve@hennepin.us>; Robert H. Byers <Robert.Byers@hennepin.us>
Subject: 2016 Regional Solicitation - Forecast AADT's

Greetings Mark,

I'm writing to request 2040 Forecast AADT information for the Regional Solicitation. Below is the list of projects with our most recent adjusted traffic counts. Project location maps are attached, in the same order as the list below:


- CSAH 15 (Shoreline Dr) Bridge Replacement (Over Browns Bay/Tanager Channel): **16,500** (2014 AADT)
- CSAH 19 (Manitou Rd/Shadywood Rd) Bridge Rehabilitation (Over Narrows Channel): **11,900** (2016 AADT)
- CSAH 23 (Marshall St NE) Reconstruction: **8,800** (2016 AADT)
- CSAH 32 (Penn Ave) Reconstruction: **12,800** (2014 AADT)
- CSAH 66 (Golden Valley Rd) Reconstruction: **11,900** (2016 AADT)
- CSAH 81 (Bottineau Blvd) Expansion (4-lane divided to 6-lane divided): **21,400** (2013 AADT)
- CSAH 81 (Broadway Ave) Bridge Replacement (Over CSAH 153 [Lowry Ave]): **12,100** (2016 AADT)
- CSAH 152 (Webber Pkwy) Reconstruction: **13,700** (2013 AADT)

Please let me know if you need any additional information, and thank you!

Sierra Saunders Multimodal Planner Hennepin County Public Works 1600 Prairie Drive, Medina, MN 55340

Office: 612.596.0364 sierra.saunders@hennepin.us

Disclaimer: If you are not the intended recipient of this message, please immediately notify the sender of the transmission error and then promptly delete this message from your computer system.



FINAL - APPROVED 07/17/09





FIGURE 4 - HISTORIC DEVELOPMENT & TRANSPORTATION PATTERNS

ACCESS MINNEAPOLIS

THE GRAND ROUNDS



April 7, 1999





Figure 2: Robbinsdale Segment of Crystal Lake Regional Trail


WEST BROADWAY AVENUE





Full Listing of Planned 2040 Bikeway System Segments


Figure 1 Planned 2040 Bikeway System Corridors Map



4.4.2 - Recommended Intersection/Crossing Improvements



3.2.4 - Existing Network of On-Street Bike and Off-Road Shared-Use Facilities





City of Robbinsdale

4100 Lakeview Avenue North • Robbinsdale • Minnesota • 55422-2280 Phone (763)531-1258 • Fax (763)531-1291 Website <u>www.robbinsdalemn.com</u>

June 22, 2016

James N. Grube, P.E. Hennepin County Engineer Transportation Department 1600 Prairie Drive Medina, Minnesota 55340

Re: Support for Regional Solicitation Application CSAH 81 (West Broadway Ave./Bottineau Blvd.) Bridge Replacement at Lowry Avenue/ Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway

Dear Mr. Grube:

The City of Robbinsdale supports Hennepin County's federal funding application through the Regional Solicitation for the proposed CSAH 81 (West Broadway Avenue/Bottineau Boulevard) bridge replacement project over Lowry Avenue/Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway.

The city supports this county project to replace the deteriorated bridges with an upgraded design. This bridge replacement project will enhance the livability and quality of life for Robbinsdale and Hennepin County residents.

Thank you for making us aware of this application effort and the opportunity to provide support. The city looks forward to working with you on this project.

Sincerely,

Marian Tail

Marcia Glick City Manager City of Robbinsdale, Minnesota



Public Works 350 S. Fifth St. - Room 203 Minneapolis, MN 55415 TEL 612.673.2352

www.minneapolismn.gov

June 20, 2016

James N. Grube, P.E. Director of Transportation and County Engineer Transportation Department 1600 Prairie Drive Medina, Minnesota 55340

Re: Support for Regional Solicitation Application CSAH 81 (West Broadway Ave./Bottineau Blvd.) Bridge Replacement at Lowry Avenue/ Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway

Dear Mr. Grube:

The City of Minneapolis supports Hennepin County's federal funding application through the Regional Solicitation for the proposed CSAH 81 (West Broadway Avenue/Bottineau Boulevard) bridge replacement project over Lowry Avenue/Oakdale Avenue and Victory Memorial Drive/Theodore Wirth Parkway.

The City of Minneapolis supports this Hennepin County project to replace the deteriorated bridges with an upgraded design. This bridge replacement project will enhance the livability and quality of life for Minneapolis and Hennepin County residents.

Thank you for making us aware of this application effort and the opportunity to provide support. The city looks forward to working with you on this project.

Sincerely,

isa K. Crnuz

Lisa Cerney Director of Public Works